

CONTINUED FROM PRECEDING PAGE

AIRPORT MANAGER: (315) 869-2676

WEATHER DATA SOURCES: AWOS-3 118.525 (315) 393-8982.

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.4 (BURLINGTON RADIO)

® BOSTON CENTER APP/DEP CON 135.25

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Boston ARTCC at 603-879-6859 .

RADIO AIDS TO NAVIGATION: NOTAM FILE MSS.

MASSENA (H) TACAN Chan 88 MSS (114.1) N44°54.87' W74°43.36' 260° 34.6 NM to fld. 198/14W.

OGIVE NDB (LOMW) 358 OG N44°42.09' W75°21.18' 269° 4.9 NM to fld. 358/13W. NOTAM FILE OGS.

LOC/DME 110.7 I-OGS Chan 44 Rwy 27. LOM OGIVE NDB. Loc/LOM unmonitored.

COMM/NAV/WEATHER REMARKS: Actf approaching from the west and landing on Rwy 09 should monitor Brockville Arprt (CNL3) UNICOM on 123.0.

OGIVE N44°42.09' W75°21.18' NOTAM FILE OGS.

MONTREAL

NDB (LOMW) 358 OG 269° 4.9 NM to Ogdensburg Intl. 358/13W.

L-32G

OLCOTT-NEWFANE (D80) 2 SW UTC-5(-4DT) N43°19.25' W78°43.74'

DETROIT

315 NOTAM FILE BUF

RWY 09-27: 2500X60 (TURF)

RWY 09: Trees.

RWY 27: Tree.

RWY 06-24: 2408X30 (TURF)

RWY 06: Trees.

RWY 24: Trees.

AIRPORT REMARKS: Attended dalgt hrs. Arprt CLOSED indef. Deer on and invof arprt. 35 ft p-line off Rwy 24 and 27 ends. Rwy 06: 72'-80' trees; across thld and along sides of rwy for 800'. Rwy 09: 31'-100' trees, across thld and along sides of rwy for 600'. Rwy 09-27 ruf and uneven.

AIRPORT MANAGER: 716-778-6700

COMMUNICATIONS: CTAF/UNICOM 122.7

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0490.

OLEAN

CATTARAUGUS CO-OLEAN (OLE)(KOLE) 10 N UTC-5(-4DT) N42°14.47' W78°22.28'

DETROIT

2135 B NOTAM FILE OLE

(OLE) (KOLE)

L-301

RWY 04-22: H4800X100 (ASPH-GRVD) S-81, D-103, 2D-168

IAP

PCN 32 F/D/X/T HIRL 0.4% up SW

RWY 04: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Thld dspld 100'. Trees.

RWY 22: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Thld dspld 200'.

Trees.

RWY 16-34: 2117X100 (TURF) 0.9% up NW

RWY 16: Tree.

RWY 34: Tree.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 04: TORA-4800 TODA-4800 ASDA-4600 LDA-4500

RWY 22: TORA-4800 TODA-4800 ASDA-4700 LDA-4500

SERVICE: FUEL 100LL, JET A+ LGT ACTVT REIL Rwy 04 and 22; PAPI

Rwy 04 and 22; HIRL Rwy 04-22; WDI—CTAF. PAPI Rwy 22

unusable byd 5 deg left of RCL.

AIRPORT REMARKS: Attended 1300-2100Z. Call AMGR for svc availability

on hol. Fuel avbl 24/7. Snow plowing and braking action and fld

condition reports not avbl when arprt is unattended. Deer on and invof

arprt. Terrain drops off on all rwy ends. Rwy 04 250' X 250' safety

area. Rwy 22, 225' X 110' safety area. Rwy 16-34 has reflective

edge and thld markings. Rwy 16-34 CLOSED winter months, soft in

spring. Unmanned actf 1 NM radius SFC-500'.

AIRPORT MANAGER: 716-557-8800

WEATHER DATA SOURCES: AWOS-3 118.375 (716) 557-2001.

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEVELAND CENTER APP/DEP CON 124.325

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0227.

RADIO AIDS TO NAVIGATION: NOTAM FILE ELZ.

WELLSVILLE (L) DME 115.85 ELZ Chan 105(Y) N42°05.38' W77°59.97' 299° 18.9 NM to fld. 2298.

DME unusable:

170°-195° byd 25 NM

LOC 109.3 I-OLE Rwy 22.

