

STONINGTON MUNI (93B) 1 NW UTC-5(-4DT) N44°10.39' W68°40.82' HALIFAX
 32 NOTAM FILE BGR
 RWY 07-25: H2099X60 (ASPH) 0.3% up W
 RWY 07: Trees.
 RWY 25: Trees. Rgt tfc.
 AIRPORT REMARKS: Unattended. Daylight use only. Use extreme care seagulls and deer on and invof arpt. Trees and brush in pri sfc some as close as 50 ft frm cntrln. Rwy 07 nrs and cntrln non-std and faded. Rwy 25 nrs and cntrln non-std.
 AIRPORT MANAGER: 207-367-2351
 COMMUNICATIONS: CTAF 122.9
 Ⓡ BANGOR APP/DEP CON 133.6
 CLEARANCE DELIVERY PHONE: For CD ctc Bangor Apch at 207-561-2500 ext 1.

 HELIPAD H1: H40X40 (ASPH)

SUGARLOAF RGNL (See CARRABASSETT on page 64)

SWANS ISLAND

BANKS (ME5) 5 N UTC-5(-4DT) N44°09.92' W68°25.69' HALIFAX
 100 NOTAM FILE BGR
 RWY 10-28: 1500X30 (GRVL) 2.0% up W
 RWY 10: Tree.
 RWY 28: Thld dsplcd 300'. Bldg.
 RUNWAY DECLARED DISTANCE INFORMATION
 RWY 10: TORA-1500 TODA-1500 ASDA-1500 LDA-1500
 RWY 28: TORA-1500 TODA-1500 ASDA-1500 LDA-1200
 AIRPORT REMARKS: Unattended. Prior to using arpt call 207-460-1113. ALL ops rstred to dalgt VFR only. Wildlife on and invof arpt. Rwy 10-28 +6 ft rock ledge 50 ft from centerline south side of arpt. Rwy 10 has +15 ft trees 50 ft rgt of cntrln, 430 ft fm thr. Rwy 10-28 sfc rough with lrg stones, steep gradients and no line of sight between ends. Rock drainage swale across 600 ft from Rwy 28, approximately 40 ft wide at centerline.
 AIRPORT MANAGER: 207-460-1113
 COMMUNICATIONS: CTAF 122.9
 Ⓡ BANGOR APP/DEP CON 133.6
 CLEARANCE DELIVERY PHONE: For CD ctc Bangor Apch at 207-561-2500 ext 1.

 HELIPAD H1: H40X40 (CONC)
 HELIPORT REMARKS: Helipad coords 44 09 54.80N 68 25 48.80W; helipad elev 86'. Ingress and egress to helipad between 130° and 320° mag.

VAN BUREN SPB (Ø5B) 0 N UTC-5(-4DT) N47°09.54' W67°55.92' HALIFAX
 440 LRA NOTAM FILE BGR
 WATERWAY NW-SE: 4000X200 (WATER)
 WATERWAY SE: Bridge.
 SEAPLANE REMARKS: Unattended. Clsd Oct 15-May 15 yearly. Dock located near base of bridge. Flight Notification Service (ADCUS) available. U.S. Customs avbl 24 hrs, 207-868-3391.
 AIRPORT MANAGER: 207-868-2886
 COMMUNICATIONS: CTAF 122.9
 CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

WALES (ME6) 2 SSW UTC-5(-4DT) N44°10.47' W70°01.14' MONTREAL
 210 NOTAM FILE BGR
 RWY 04-22: 2100X80 (TURF)
 RWY 04: Ground.
 RWY 22: Tree.
 AIRPORT REMARKS: Unattended. Arpt CLOSED Nov-May, exc for skiing. Rwy 04-22 soft in spring, call prior to ldg 207-754-1372. Acft should mnt 122.8 invof arpt. 1239' MSL twr 7000' SE and 968' MSL twr 9600' SSE of arpt. Rwy 04 nstd markings, has white plastic barrel markers along side of rwy with thld marked with single plastic white barrel. Rwy 22 nstd markings, has white plastic barrel markers along side of rwy with thld marked with single plastic white barrel. FCLP equipment directly adjacent to left side of Rwy 10 1335-1725' approach end. FCLP equipment directly adjacent to left side of Rwy 28 1340-1725' from approach end.
 AIRPORT MANAGER: 207-754-6322
 COMMUNICATIONS: CTAF 122.9
 CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.