OREGON

PINEHURST STATE (24S) 1 SW UTC-8(-7E	DT) N42°06.61′ W122°22.99′	KLAMATH FALLS
3643 NOTAM FILE MMV		
RWY 04-22: H2800X30 (ASPH) 2.0% up SW		
RWY 04: Trees.		
RWY 22: Trees.		
AIRPORT REMARKS: Unattended. Surface conditions not reported. Irregular winter maintenance. Arpt may be clsd by snow. Strong winds from any direction will likely cause low-level turbulence. Rwy 04–22 12 ft trees wi 25 feet of cntrln full len. Rwy 22 slopes up to the SW, with abrupt 4% rise on SW half of rwy. Owner advises contact Oregon Dept. of Aviation 503–378–4880 prior to use. AIRPORT MANAGER: 503-378-4880 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.		
PITTSBURG LANDING (See IMNAHA on page 178)	

PORTLAND

PORTLAND DOWNTOWN HELIPORT (61J) 0 N UTC-8(-7DT) N45°31.52´W122°40.26´
SEATTLE 78 B NOTAM FILE MMV
HELIPAD H1: 80X80 (ROOF-TOP) S-25 PERIMETER LGTS
SERVICE: LGT For heliport PLASI when approaching flt apch and tkf 020-activate CTAF 3 times. When approaching flt apch and tkf 025-activate CTAF 7 times.
HELIPORT REMARKS: Unattended. +199´ radio twr (Igtd) 4950´ E of heliport in flt apch and tkf 025°. Helipad H1 yellow perimeter Igts, blue centerline twy Igts to helipads. Helipad H1 single heliport with 4 flt apchs 162°/220°/248°/295° and tkf 040°/068°/115°. Ldg fee.
AIRPORT MANAGER: 503-823-6677
COMMUNICATIONS: CTAF/UNICOM 123.075
CLEARANCE DELIVERY PHONE: FOR CD ctc Portland Apch at 503-493-7545.