

FRIEDMAN MEML (See HAILEY on page 57)

FROSTENSON FLD (See FAIRFIELD on page 53)

GARDEN VALLEY (U88) 2 SE UTC-7(-6DT) N44°04.02' W115°55.88'

SALT LAKE CITY

3177 NOTAM FILE BOI

RWY 10-28: 3850X125 (TURF) 1.4% up E

RWY 10: Fence.

RWY 28: Fence.

AIRPORT REMARKS: Unattended. USFS heli ops adj to SE end of arpt. Watch for sprinkler heads on rwy. Arpt located in mountain valley. No winter maintenance. Recommend ldg Rwy 10, tkf Rwy 28, if winds allow. Rwy 10-28 edges and thlds marked with white rocks. No telephone avbl at arpt.

AIRPORT MANAGER: 208-334-8775

COMMUNICATIONS: CTAF 122.9

GLENNS FERRY MUNI (U89) 1 SW UTC-7(-6DT) N42°56.62' W115°19.81'

SALT LAKE CITY

2536 B NOTAM FILE BOI

L-11C

RWY 08-26: H3050X60 (ASPH) MIRL

RWY 26: Trees.

SERVICE: LGT ACTIVATE rotating bcn, MIRL Rwy 08-26—CTAF.

AIRPORT REMARKS: Unattended. Rwy 08-26 distance to go markers every 1000' south side of rwy. Rwy 08-26 white reflectors on both edges of rwy, green reflectors on both thlds.

AIRPORT MANAGER: 208-899-1177

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD etc MUO RAPCON at 208-828-6096 when opn. Salt Lake ARTCC at 801-320-2568 when clsd.

RADIO AIDS TO NAVIGATION: NOTAM FILE TWF.

TWIN FALLS (VL) (H) VORTACW 113.1 TWF Chan 78 N42°28.79' W114°29.37' 289° 46.4 NM to fld. 4149/18E.

VOR unusable:

000°-010° byd 40 NM blo 7,000'

000°-010° byd 50 NM

011°-015° byd 40 NM

040°-091° byd 40 NM

092°-102° byd 40 NM blo 16,500'

092°-102° byd 77 NM

103°-106° byd 40 NM

107°-117° byd 40 NM blo 14,000'

107°-117° byd 64 NM blo 22,000'

118°-171° byd 40 NM

120°-160° byd 35 NM blo 12,000'

172°-182° byd 40 NM blo 13,000'

172°-182° byd 55 NM

183°-185° byd 40 NM

186°-196° byd 40 NM blo 10,600'

186°-196° byd 57 NM

197°-230° byd 40 NM

TACAN AZIMUTH unusable:

120°-160° byd 35 NM blo 12,000'

DME unusable:

120°-160° byd 35 NM blo 12,000'

