
WOODWORTH (1R4) 2 S UTC-6(-5DT) N31°07.58' W92°30.08'

HOUSTON

140 B NOTAM FILE DRI

L-21B, 22E

RWY 01-19: H3100X75 (ASPH) S-12 MIRL**RWY 01:** SAVASI(S2R)—GA 4.0° TCH 20'. Trees.**RWY 19:** SAVASI(S2R)—GA 4.0° TCH 20'. Trees.**SERVICE:** LGT SAVASI Rwy 01 and Rwy 19 OTS indef. Windssock lghts OTS indef. ACTIVATE MIRL Rwy 01-19—122.8.**AIRPORT REMARKS:** Unattended. Helicopter tfc on fld. Numerous 2 inch cracks on rwy. Night ops not recommended due to phys obstrn (high tree line on both ends of rwy) and lightings issues.**AIRPORT MANAGER:** 225-952-8074**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Polk Apch at 337-531-2352.**RADIO AIDS TO NAVIGATION:** NOTAM FILE AEX.**ALEXANDRIA (H) VORTACW** 116.1 AEX Chan 108 N31°15.40' W92°30.06' 177° 7.8 NM to fld. 76/3E.

VOR unusable:

035°-065° blo 2,000'

066°-094° byd 35 NM blo 3,000'

185°-200° byd 35 NM blo 3,000'

201°-214° byd 35 NM blo 2,000'

215°-260° blo 2,000'

261°-285° byd 35 NM blo 2,000'

357°-034° byd 35 NM blo 3,000'