


**FLOYDADA MUNI** (41F) 1 N UTC-6(-5DT) N34°00.09' W101°19.82'  
 3187 B NOTAM FILE FTW  
**RWY 17-35:** H4600X60 (ASPH) S-15 MIRL  
**RWY 17:** PAPI(P2L)—GA 3.0° TCH 40'.  
**RWY 35:** PAPI(P2L)—GA 3.0° TCH 39'. Bldg. Rgt tfc.  
**SERVICE:** FUEL 100LL, JET A LGT Dusk-Dawn. MIRL Rwy 17-35 preset to low intst; to incr intst or actv—CTAF.  
**AIRPORT REMARKS:** Attended Mon-Sat 1400-0000Z†. Extsv aerial ag ops.  
**AIRPORT MANAGER:** 806-983-2314  
**COMMUNICATIONS:** CTAF/UNICOM 122.8  
 (R) LUBBOCK APP/DEP CON 119.2 119.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Fort Worth ARTCC at 817-858-7584.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE PVW.  
**PLAINVIEW (VL) (L) VORW/DME** 112.9 PVW Chan 76 N34°05.17' W101°47.41' 091° 23.5 NM to fld. 3400/11E.

DALLAS-FT WORTH  
 L-6H  
 IAP



**FLUFY** N31°13.13' W94°49.51' NOTAM FILE LFK.  
 NDB (LOMW) 350 LF 075° 4.0 NM to Angelina Co. 205/2E. NDB unmonitored.

HOUSTON

**FLYIN TIGER** (See ANGLETON on page 250)

**FLYING C** (See SANGER on page 421)

**FLYING H RANCH** (See WHITESBORO on page 446)

**FLYING V RANCH** (See LOUISE on page 368)

**FOLLETT/LIPSCOMB CO** (T93) 1 E UTC-6(-5DT) N36°26.45' W100°07.43'  
 2601 NOTAM FILE FTW  
**RWY 17-35:** H4073X60 (ASPH) S-18 1.7% up S  
**RWY 17:** P-line.  
**RWY 35:** Hill.  
**AIRPORT REMARKS:** Unattended. No line of sight btn rwy ends. Rwy 17-35 13 ft wide strip of pavement along west edge of rwy failed, will not support listed wheel weight. Rwy 17-35 extensive pavement cracking with vegetation growing through. Loose stones on rwy. Rwy 17 and Rwy 35 no pavement mrkgs.  
**AIRPORT MANAGER:** 806-653-2601  
**COMMUNICATIONS:** CTAF 122.9  
 (R) KANSAS CITY CENTER APP/DEP CON 126.95  
**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE GAG.  
**MITBEE (VH) (H) VORTACW** 115.6 MMB Chan 103 N36°20.62' W99°52.81' 286° 13.2 NM to fld. 2426/10E.

WICHITA  
 L-15C

