

CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE VPS.

WARRINGTON (T) TACAN Chan 2 DWG (134.5) N30°28.69' W86°31.25' 003° 10.2 NM to fld. 120/3W.

ILS 111.7 I-EGJ Rwy 18. Class IT. Unmonitored when ATCT clsd.

COMM/NAV/WEATHER REMARKS: UHF equipped acft must use UHF in Duke tfc pat.

DUNNELLON

MARION CO (X35) 5 E UTC-5(-4DT) N29°03.71' W82°22.60'

65 B NOTAM FILE GNV

RWY 05-23: H5000X100 (ASPH) PCN 13 F/B/Y/T MIRL

RWY 05: PAPI(P4L)—GA 3.0° TCH 28'. Trees.

RWY 23: PAPI(P4L)—GA 3.0° TCH 27'. Tree.

RWY 10-28: H4701X60 (ASPH) PCN 12 F/A/Y/T MIRL

RWY 10: Trees.

RWY 28: Trees.

SERVICE: S4 FUEL 100LL, JET A+ LGT ACTVT PAPI Rwy 05 and 23; MIRL Rwy 05-23 and 10-28—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1300-2100Z±. Credit card fuel avbl H24.

AIRPORT MANAGER: 352-465-8545

COMMUNICATIONS: CTAF/UNICOM 122.8

® JACKSONVILLE APP/DEP CON 118.6

CLEARANCE DELIVERY PHONE: For CD ctc Jacksonville Apch at 904-741-0284.

RADIO AIDS TO NAVIGATION: NOTAM FILE OCF.

OCALA (VL) (L) VORTAC 113.7 OCF Chan 84 N29°10.65' W82°13.58' 229° 10.5 NM to fld. 78/OE.

TACAN AZIMUTH unusable:

025°-078°

329°-350°

351°-024° byd 28NM

VOR unusable:

010°-024° byd 40 NM

030°-037° byd 40 NM

053°-060° byd 40 NM

065°-077° byd 40 NM

094°-108° byd 40 NM blo 3,000'

094°-108° byd 66 NM

127°-137° byd 40 NM

157°-171° byd 40 NM blo 13,000'

157°-171° byd 75 NM

177°-187° byd 40 NM blo 2,000'

177°-187° byd 54 NM

193°-210° byd 40 NM

219°-244° byd 40 NM

277°-298° byd 40 NM

325°-335° byd 40 NM blo 10,000'

325°-335° byd 76 NM

352°-005° byd 111 NM

352°-005° byd 40 NM blo 12,000'

COMM/NAV/WEATHER REMARKS: Wx adv, click 4 times on CTAF.

JACKSONVILLE

H-8H, L-21D, 24F

IAP

