

MOCKSVILLE

TWIN LAKES (8A7) 5 NE UTC-5(-4DT) N35°54.89' W80°27.41'

818 B NOTAM FILE RDU

RWY 09-27: H2943X50 (ASPH) S-12.5 RWY LGTS(NSTD)

1.5% up E

RWY 09: PAPI(P2L)—GA 3.5° TCH 49'. Trees.

RWY 27: Trees.

SERVICE: S4 FUEL 100LL OX 4 LGT Rwy 09-27 nstd lighting due to number and location.

AIRPORT REMARKS: Attended 1300-2200Z±. Deer/migratory birds occasionally on arpt. For after hrs svc ctc 336-998-2126. 100LL 24 hr self service with credit card. Rwy 09 18' drop-off 150' from thld left and right of centerline. Rwy 09 uphill grade. Rwy 09-27 markings nonstandard due to size and location.

AIRPORT MANAGER: 336-998-8101

COMMUNICATIONS: CTAF/UNICOM 122.7

® GREENSBORO APP/DEP CON 124.35

CLEARANCE DELIVERY PHONE: For CD ctc Greensboro Apch at 336-333-5119.

RADIO AIDS TO NAVIGATION: NOTAM FILE GSO.

GREENSBORO (VH) (H) VORTAC 116.2 GSO Chan 109 N36°02.74'

W79°58.58' 255° 24.7 NM to fld. 908/3W.

TACAN AZIMUTH unusable:

255°-290° byd 10 NM blo 6,000'

VOR unusable:

010°-015° byd 40 NM

072°-076° byd 40 NM

083°-093° byd 40 NM blo 6,000'

083°-093° byd 93 NM

107°-111° byd 40 NM

118°-156° byd 40 NM

157°-167° byd 40 NM blo 3,600'

157°-167° byd 48 NM

168°-180° byd 40 NM

196°-199° byd 40 NM

240°-250° byd 40 NM

260°-276° byd 40 NM

277°-288° byd 40 NM blo 3,500'

277°-288° byd 47 NM blo 6,000'

277°-288° byd 56 NM

289°-302° byd 40 NM blo 5,000'

289°-302° byd 55 NM

303°-317° byd 40 NM blo 5,200'

303°-317° byd 55 NM

318°-354° byd 40 NM

CHARLOTTE

L-25D, 36F

IAP

