

MORRIS MUNI/JAMES R WASHBURN FLD (C09) 4 N UTC-6(-5DT) N41°25.49' W88°25.12'

CHICAGO

585 B NOTAM FILE C09

H-5E, L-28H, A

RWY 18-36: H501X75 (ASPH) S-4, D-125 MIRL 0.4% up N

IAF

RWY 18: REIL. PAPI(P4L)—GA 3.0° TCH 44'.

RWY 36: REIL. PAPI(P4R)—GA 3.0° TCH 43'.

SERVICE: S4 FUEL 100LL, JET A, A+ LGT MIRL Rwy 18-36 preset on low ints; to increase ints and ACTIVATE REIL Rws 18 and 36—CTAF. MIRL Rwy 18-36; REIL Rwy 18 and Rwy 36 on photo cell.

AIRPORT REMARKS: Attended 1200-0000Z.**AIRPORT MANAGER:** 815-942-1600**WEATHER DATA SOURCES:** AWOS-3 118.175 (815) 941-1815.**COMMUNICATIONS:** CTAF/UNICOM 122.8

JOLIET RCO 122.1R 112.3T (KANKAKEE RADIO)

Ⓡ CHICAGO APP/DEP CON 119.35


CLEARANCE DELIVERY PHONE: For CD ctc Chicago Apch at 847-289-0926.**RADIO AIDS TO NAVIGATION:** NOTAM FILE JOT.

JOLIET (H) (H) VOR/DME 112.3 JOT Chan 70 N41°32.79'

W88°19.10' 210° 8.6 NM to fld. 591/2E.

VOR unusable:

072°-090° byd 34 NM blo 3,000'

**MOUNT CARMEL MUNI** (AJG)(KAJG) 12 N UTC-6(-5DT) N38°36.39' W87°43.60'

ST LOUIS

429 B NOTAM FILE AJG

L-27D

RWY 13-31: H4500X75 (ASPH) S-54.5, D-71 PCN 21 F/D/X/T MIRL

IAF

RWY 13: REIL. PVASI(P5IL)—GA 3.0° TCH 23'.

RWY 31: REIL. PVASI(P5IL)—GA 3.0° TCH 25'.

RWY 04-22: H4000X100 (ASPH) S-40.5, D-54 PCN 16 F/D/X/T MIRL

RWY 04: REIL. PVASI(P5IL)—GA 3.0° TCH 23'.

RWY 22: REIL. PVASI(P5IL)—GA 3.0° TCH 22'.

SERVICE: S2 FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 04, Rwy 13, Rwy 22 and Rwy 31; PVASI Rwy 04, Rwy 13, Rwy 22 and Rwy 31; MIRL Rwy 13-31—CTAF. MIRL Rwy 04-22 preset on low ints to increase ints—CTAF. Rwy 04 PVASI unusable byd 5° left and right of cntrln. Rwy 22 PVASI unusable byd 5° left, right of cntrln. Rwy 13 PVASI unusable byd 5° left, right of cntrln. Rwy 31 PVASI unusable byd 5° left and right of cntrln.


AIRPORT REMARKS: Attended 1400-2300Z. Self serve fuel avbl 24 hrs with credit card.**AIRPORT MANAGER:** 618-948-2413**WEATHER DATA SOURCES:** AWOS-3 134.900 (618) 948-2184.**COMMUNICATIONS:** CTAF/UNICOM 122.7

Ⓡ EVANSVILLE APP/DEP CON 125.6

Ⓡ INDIANAPOLIS CENTER APP/DEP CON 128.3

CLEARANCE DELIVERY PHONE: For CD ctc Evansville Apch at 812-436-4690, when Apch clsd ctc Indianapolis ARTCC at 317-247-2411.**RADIO AIDS TO NAVIGATION:** NOTAM FILE LWV.

LAWRENCEVILLE (T) DME 108.8 LWV Chan 25 N38°46.19' W87°36.23' 211° 11.4 NM to fld. 430.

**MOUNT HAWLEY AUXILIARY** (See PEORIA on page 78)**MOUNT MORRIS****OGLE CO** (C55) 2 SE UTC-6(-5DT) N42°02.22' W89°23.58'

CHICAGO

929 B TPA—See Remarks NOTAM FILE IKK

RWY 09-27: 2640X200 (TURF) LIRL(NSTD)

SERVICE: LGT ACTIVATE nstd LIRL Rwy 09-27 and rotating bcn—CTAF. Rwy 09-27 nstd LIRL due to spacing; ints and non-frangible—orange cones adjacent to lights.

AIRPORT REMARKS: Unattended. Rwy 09-27 not plowed during winter months; use at own risk. TPA—1329 (400) ultralights, 1729 (800) single engine. +10' corn may be on rwy ends during growing season.

AIRPORT MANAGER: 815-973-3234**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Chicago ARTCC at 630-906-8921.