

ELLENVILLE**JOSEPH Y RESNICK** (N89) 1 NE UTC-5(-4DT) N41°43.73' W74°22.61'**NEW YORK**

290 B NOTAM FILE ISP

L-33B, 34I

RWY 04-22: H3839X75 (ASPH) MIRL

IAP

RWY 04: REIL. PAPI(P2L)—GA 3.5° TCH 40'. Trees.**RWY 22:** REIL. PAPI(P2L)—GA 3.0° TCH 39'. Thld dspcd 309'. Rgt ttc.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 04:** TORA-3838 TODA-3838 ASDA-3838 LDA-3538**RWY 22:** TORA-3838 TODA-3838 ASDA-3838 LDA-3538**SERVICE:** S2 FUEL 100LL LGT ACTIVATE REIL Rwy 04 and Rwy 22, PAPI Rwy 04 and Rwy 22, MIRL Rwy 04-22—CTAF.**AIRPORT REMARKS:** Attended 1300Z±-dusk. Rwy 04 +60' trees 200' from rwy 191' rgt. Rwy 22 +8' fence crosses runway, 24' from thld. Avoid overflight of school and village when taking off Rwy 22 or apch to Rwy 04, helicopter operations follow fixed wing flight pattern. Avoid overflight of hospital and school bldgs approx 1 mile southwest of Rwy 22 and prison approx 1/2 mile northeast of arpt. Cold temperature airport. Altitude correction required at or below -6C.**AIRPORT MANAGER:** 845-647-7800**COMMUNICATIONS:** CTAF/UNICOM 122.8® **NEW YORK APP/DEP CON** 132.75**CLEARANCE DELIVERY PHONE:** For CD ctc: New York Apch at 516-683-2448**RADIO AIDS TO NAVIGATION:** NOTAM FILE ISP.**KINGSTON (VL) (L) VOR/DME** 117.6 IGN Chan 123 N41°39.93' W73°49.33' 291° 25.2 NM to fld. 581/12W.

VOR unusable:

008°-018° byd 40 NM blo 4,000'

008°-018° byd 70 NM

020°-123° byd 40 NM

045°-050° byd 35 NM blo 4,300'

070°-140° byd 30 NM blo 3,400'

082°-092° byd 20 NM blo 4,000'

082°-092° byd 35 NM blo 5,500'

130°-148° byd 40 NM

203°-216° byd 30NM

243°-253° byd 40 NM

275°-310° byd 40 NM

311°-321° byd 40 NM blo 6,000'

311°-321° byd 64 NM

322°-001° byd 40 NM

