

**METALINE FALLS****SULLIVAN LAKE STATE** (Ø9S) 3 SE UTC-8(-7DT) N48°50.45' W117°17.04'

SEATTLE

2614 NOTAM FILE SEA

**RWY 16-34:** 1765X100 (TURF)**RWY 16:** Trees.**RWY 34:** Sign.**AIRPORT REMARKS:** Unattended. Arpt clsd 1 Oct-1 June exc for apvd mil and public safety/law enforcement helicopter ops.

Vehicles, pedestrians, and animals on and invof arpt. Watch for gnd squirrel holes in rwy. Rwy 16-34 sfc rough. Trees both sides in transition sfc. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acft accidents/incidents ctc WA state emergency operations center 800-258-5990. Gnd drops rapidly byd Rwy 16-34 ends. Rwy marked with reflectors dur dates arpt is open. 2 wind socks, one on each rwy end.

**AIRPORT MANAGER:** (360) 618-2477**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**METHOW VALLEY STATE** (See WINTHROP on page 291)**MONROE****FIRST AIR FLD** (W16) 2 NW UTC-8(-7DT) N47°52.28' W121°59.71'

SEATTLE

50 NOTAM FILE SEA

**RWY 07-25:** H2087X34 (ASPH) RWY LGTS(NSTD)**RWY 07:** P-line. Rgt tfc.**RWY 25:** Thld dspcld 500'. Trees.**SERVICE:** S4 LGT SS-SR. Solar powered lighting.

**AIRPORT REMARKS:** Attended Oct-Mar 1700Z†-dark, Apr-Sept 1700-0300Z‡. Parachute Jumping. Tran tie downs have no ropes, pilots must supply own. Additional tran parking avbl SE corner of rwy. Rwy 25 acft parked in primary sfc. Rwy 07 numbers 200' E of dspcld thr; numbers only; no cntrln. Word "MONROE" painted midfield on rwy. Rwy 07-25 markings are faded.

**AIRPORT MANAGER:** 425-239-8791**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle Apch at 206-214-4722.**MORTON****STROM FLD** (39P) 0 SE UTC-8(-7DT) N46°33.02' W122°16.00'

SEATTLE

941 B NOTAM FILE SEA

**RWY 07-25:** H1810X40 (ASPH) MIRL**RWY 07:** Thld dspcld 200'. P-line.**SERVICE:** LGT ACTIVATE MIRL Rwy 07-25 and rotating bcn—CTAF.

**AIRPORT REMARKS:** Unattended. Trees near rwy. Trees, stream and brush in prim sfc. Deer and elk on and invof rwy. Ditch parallel rwy on Eastside. Slp on N side on rwy mid-field beginning at shoulder. Rwy 07-25 markings faded. Rwy 07-25 wdspr raveling and alligator cracking.

**AIRPORT MANAGER:** (360) 496-5210**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.