424 TEXAS

```
SANGER
     FLYING C (T87) 5 SW UTC-6(-5DT) N33°20.53′ W97°16.20′
                                                                                                      DALLAS-FT WORTH
        775 NOTAM FILE FTW
        RWY 09-27: 1650X90 (TURF)
          RWY 09: Fence.
          RWY 27: Trees.
        RWY 17-35: 1400X140 (TURF)
          RWY 17: Trees.
          RWY 35: Trees.
        AIRPORT REMARKS: Unattended. For fld condition call arpt manager. Occasional livestock on fld.
        AIRPORT MANAGER: 972-978-7127
        COMMUNICATIONS: CTAF 122 9
        CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.
     IRONHEAD (T58) 3 SW UTC-6(-5DT) N33°19.91′ W97°13.82′
                                                                                                      DALLAS-FT WORTH
        715 NOTAM FILE FTW
        RWY 18-36: 2500X200 (TURF)
          RWY 18: Fence.
          RWY 36: Tree
        AIRPORT REMARKS: Unattended. Wildlife on and invof of arpt. Rwy 18-36 soft when wet, call for fld cond. Rwy 18-36 thld
          and edges marked with white tires. Arpt CLOSED to helicopter training. North 700' Rwy 18-36 slopes down 25', rwy
          ends not visible from opposite end.
        AIRPORT MANAGER: 940-458-7348
        COMMUNICATIONS: CTAF 122.9
        CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.
     VULTURES ROW (6X8) 7 E UTC-6(-5DT) N33°20.40′ W97°06.18′
                                                                                                      DALLAS-FT WORTH
        710 NOTAM FILE FTW
        RWY 18-36: 2700X50 (TURF)
          RWY 18: Tree
          RWY 36: Trees
        AIRPORT REMARKS: Unattended. Rwy 18-36 soft when wet, call for FICONS. Rwy 18-36 width mowed to 15 ft wide drg hay
          season. Rwy 18 +37 ft powerlines mkd 110 ft fm thr xng cntrln. Helicopter operations prohibited. No student pilots. Do
          not overfly house drctly N of rwy.
        AIRPORT MANAGER: 940-453-8126
        COMMUNICATIONS: CTAF 122.9
        CLEARANCE DELIVERY PHONE: For CD ctc Regional Apch at 972-615-2799.
                                                                                                          BROWNSVILLE
     SANTA ELENA U38 N26°49.26′ W98°29.10′/313
                                                                                                                L-20H
      AWOS-3T 135.975 U38 AWOS is associated with airport 38XS.
     SCHOLES INTL AT GALVESTON (See GALVESTON on page 321)
SFGUIN
                                                                                                          SAN ANTONIO
     HUBER AIRPARK CIVIC CLUB LLC (E7Ø) 2 NW UTC-6(-5DT) N29°36.14′ W97°59.43′
        556 B NOTAM FILE SJT
                                                                                                                I-19C
        RWY 18-36: H3415X50 (ASPH)
                                      LIRL
          RWY 18: Tree.
        SERVICE: FUEL 100LL LGT Actvt LIRL Rwy 18-36-CTAF. Rwy 18-36 only cntr 3285 lgtd.
        AIRPORT REMARKS: Mon-Fri 1400-2300Z‡. 100LL self-serve. Rwy 18-36 mag brg 174-354.
        AIRPORT MANAGER: 830-379-9800
        COMMUNICATIONS: CTAF 122 9
        CLEARANCE DELIVERY PHONE: For CD ctc San Antonio Apch at 210-805-5516.
        RADIO AIDS TO NAVIGATION: NOTAM FILE SAT.
          SAN ANTONIO (VH) (H) VORTACW 116.8 SAT Chan 115 N29°38.64′ W98°27.68′ 088° 24.7 NM to fld. 1159/8E.
          VOR unusable:
            018°-022° byd 40 NM
            028°-032° byd 40 NM
            342°-347° byd 40 NM
            355°-002° byd 40 NM blo 18,000′
```