

RIO VISTA MUNI (O88) 3 NW UTC-8(-7DT) N38°11.60' W121°42.22'

SAN FRANCISCO

23 B NOTAM FILE RIU

L-2F, 3A, A

RWY 07-25: H4199X75 (ASPH) S-30 MIRL

RWY 07: REIL. PAPI(P2L)—GA 4.0° TCH 40'.

RWY 25: REIL. PAPI(P2L)—GA 4.0° TCH 40'. Rgt tfc.

RWY 15-33: H2199X60 (ASPH) S-12.5 MIRL

RWY 15: REIL. PAPI(P2L)—GA 4.0° TCH 40'. Pole.

RWY 33: REIL. PAPI(P2L)—GA 4.0° TCH 40'. Rgt tfc.

SERVICE: FUEL 100LL LGT ACTVT REIL Rwy 07, 15, 25 and 33; PAPI Rwy 07, 15, 25 and 33; MIRL Rwy 07-25 and 15-33; Perimeter H1—CTAF.

NOISE: Noise sensitive area N of Rwy 33. Do not overfly ranch and corrals off Rwy 33. All rwys climb to 700' before turns.

AIRPORT REMARKS: Attended Mon-Thu 1600-0100Z†. Fast pay fuel system avbl 24 hours. Rwy 25 calm wind rwy.

AIRPORT MANAGER: 707-249-7510

WEATHER DATA SOURCES: AWOS-AV 127.075 (707) 374-5396.

COMMUNICATIONS: CTAF/UNICOM 122.725

Ⓡ TRAVIS APP/DEP CON 119.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAC.

SACRAMENTO (VH) (H) VORTACW 115.2 SAC Chan 99 N38°26.62' W121°33.10' 189° 16.6 NM to fld. 3/17E.

VOR unusable:

031°-041° byd 40 NM blo 5,000'

031°-041° byd 45 NM blo 18,000'

157°-169° byd 40 NM blo 4,500'

157°-169° byd 56 NM blo 18,000'

246°-251° byd 40 NM

252°-262° byd 40 NM blo 7,000'

252°-262° byd 65 NM

263°-269° byd 40 NM

353°-013° byd 40 NM blo 5,000'

353°-013° byd 49 NM blo 5,500'

353°-013° byd 58 NM

.....
HELIPAD H1: H180X180 (CONC) PERIMETER LGTS

HELIPAD REMARKS: No autorotations, hovering auto's or running landings to pavement. Helicopter tfc to helipad remain S of arpt 500'. When wind favors Rwy 15-33 helicopters may use apron area W of Rwy 15-33, remain W of arpt 500'.

