


**CINCINNATI MUNI/LUNKEN FLD** (LUK)(KLUK) 3 SE UTC-5(-4DT) N39°06.18' W84°25.06'CINCINNATI  
H-10G, L-27E  
IAP, AD482 B LRA Class IV, ARFF Index A NOTAM FILE LUK  
RWY 03-21: H6101X150 (ASPH-GRVD) S-60, D-70, 2D-140  
PCN 42 R/C/X/T HIRLRWY 03: REIL. PAPI(P4R)—GA 3.0° TCH 44'. RVR-R Tree.  
RWY 21: MALS R. PAPI(P4L)—GA 3.0° TCH 39'. RVR-T Trees.  
RWY 07-25: H5127X100 (ASPH-GRVD) S-11, D-20, 2D-55  
PCN 38 R/C/X/T MIRLRWY 07: Thld dspclcd 439'. Tree.  
RWY 25: VASI(V4L)—GA 3.0° TCH 40'.**RUNWAY DECLARED DISTANCE INFORMATION**RWY 03: TORA-6101 TODA-6101 ASDA-6101 LDA-6101  
RWY 21: TORA-6101 TODA-6101 ASDA-6101 LDA-6101  
**SERVICE:** S4 FUEL 100LL, JET A+ OX 1 LGT When ATCT clsd actvt  
or incr instst MALS R Wwy 21; HIRL Wwy 03-21—CTAF. HIRL Wwy  
03-21 preset on med instst. Wwy 07-25 PCL unavbl. Wwy 03 PAPI  
unusbl byd 7 degs left of cntrln. Rotating bcn located 1.7 NM E of  
arprt.**NOISE:** Noise abatement procs in efct call amgr. Acft maint runups rstdr  
btn 0200-1200Z†.**AIRPORT REMARKS:** Attended continuously. Deer and birds on and invof  
arprt. Fuel A+ C513-871-2020. Clsd scheduled ACR ops greater  
than 9 pax seats. 48 hr PPR for unsched ACR ops with gtr than 30 passenger seats call amgr. Wwy 07-25 clsd to unsked  
acr ops gtr than 30 pax seats. AER Wwy 25 and Wwy 21 are closely lctd; vfy cor wwy with compass hdg bfr dep. Arprt sfc  
cond unmon dly 0400-1200Z†. Twy D, E, G, & H clsd to unsked acr ops gtr than 30 pax seats. Twy H not vsb fm ATCT,  
ctc ground control. When ATCT clsd, use CTAF. Ldg fee. Flight Notification Service (ADCUS) available.**AIRPORT MANAGER:** 513-352-6340**WEATHER DATA SOURCES:** ASOS (513) 321-6291**COMMUNICATIONS:** CTAF 118.7 ATIS 123.6 UNICOM 122.95

Ⓡ APP/DEP CON 121.0

**LUNKEN TOWER** 118.7 (1200-0400Z†) **GND CON/CLNC DEL** 121.9 **CLNC DEL** 124.9 (when twr closed)**AIRSPACE:** CLASS D svc 1200-0400Z†; other times CLASS E.**VOR TEST FACILITY (VOT)** 108.4**RADIO AIDS TO NAVIGATION:** NOTAM FILE CVG.(L) (L) **VORTACW** 117.3 CVG Chan 120 N39°00.96' W84°42.20' 073° 14.3 NM to fld. 878/4W.**ILS/DME** 110.9 I-LUK Chan 46 Wwy 21. Class IA. Unmonitored when ATCT clsd. DME unusable byd 25° left of  
course.**COMM/NAV/WEATHER REMARKS:** Emerg frequency 121.5 not avbl at twr. Cust in tempo fac; cust fac reqs must be smtd to arprt  
first by calling 513-709-2761 or email #DOTE-AVIATION@CINCINNATI.OH.GOV.**CINCINNATI WEST** (See HARRISON on page 290)**CINCINNATI/NORTHERN KENTUCKY INTL** (See COVINGTON on page 278)**CIRCLEVILLE****PICKAWAY CO MEML** (CYO)(KCYO) 5 S UTC-5(-4DT) N39°30.96' W82°58.93'CINCINNATI  
L-29A  
IAP

685 B NOTAM FILE DAY

RWY 01-19: H4346X75 (ASPH) S-30, D-40 MIRL 0.5% up N

RWY 19: REIL. PAPI(P4R)—GA 3.0° TCH 24'.

**SERVICE:** FUEL 100LL, JET A LGT ACTIVATE REIL Wwy 19; PAPI Wwy 19; MIRL—CTAF.**AIRPORT REMARKS:** Unatndd. Fuel: 100LL and Jet A avbl H24 via credit card.**AIRPORT MANAGER:** 740-474-5145**COMMUNICATIONS:** CTAF/UNICOM 122.7

Ⓡ COLUMBUS APP/DEP CON 134.0

**CLEARANCE DELIVERY PHONE:** For CD ctc Columbus Apch at 614-338-8537.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DAY.**APPLETON (VH) (H) VORTAC** 116.7 APE Chan 114 N40°09.06' W82°35.30' 212° 42.2 NM to fld. 1354/6W.

VOR unusable:

025°-030°

TACAN AZIMUTH unusable:

075°-095°

110°-115°

DME unusable:

075°-080°

**YELLOW BUD (T) VORW** 112.5 XUB N39°31.61' W82°58.68' at fld. 689/5W.