

**CONCORD MUNI** (CON)(KCON) P (ARNG) 2 E UTC-(-4DT) N43°12.16' W71°30.14' NEW YORK  
H-11D, 12K, L-32H  
IAP, AD  
 342 B NOTAM FILE CON  
**RWY 17-35:** H6005X100 (ASPH) S-43, D-60 HIRL  
**RWY 17:** PAPI(P4L)—GA 3.0° TCH 50'. Thld displcd 641'. Tree.  
**RWY 35:** MALSR. VASI(V4L)—GA 3.0° TCH 50'. Trees.  
**RWY 12-30:** H3200X75 (ASPH) S-30 MIRL  
**RWY 12:** Antenna.  
**RWY 30:** Ground.  
**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** ACTIVATE MALSR Rwy 35, HIRL Rwy 17-35, MIRL Rwy 12-30—CTAF. **MILITARY—FUEL** J8(Mil)—PPR (NC-100LL - Avbl H24 with credit card; A - Avbl 1230-2200Z†, OT fone C603-228-2267 and flw prompts.)  
**AIRPORT REMARKS:** Attended 1200-2200Z†, exc Thanksgiving, Christmas, and New Years Day. Wildlife on and invof arpt. Hvy hel act 1 NM ESE of arpt 800 ft & blw. Self serve 100LL avbl 24 hrs with credit card. For Jet A aft hrs call 603-228-2267 & flw prompts. Rwy 35 designated calm wind rwy. Day & ngt VFR hel ops to & fm New Hampshire State Police hngr. Ops on National Guard twy & ramp prohibited wo prior cdn due to scy. Mil twy & ramp PCN R/A/W/T. Ops off paved sfcs prohibited due to conservation mgmt acts. Compass rose calibrated 2014.  
**AIRPORT MANAGER:** 603-228-2267  
**WEATHER DATA SOURCES:** ASOS 132.325 (603) 224-6558.  
**COMMUNICATIONS:** CTAF/UNICOM 122.7  
**RCO** 122.2 (BANGOR RADIO)  
 Ⓡ **BOSTON APP/DEP CON** 127.35  
**CLNC DEL** 133.65  
**CLEARANCE DELIVERY PHONE:** For CD ctc Boston Apch at 603-594-5552.  
**AIRSPACE:** CLASS E.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE CON.  
**(L) VOR/DME** 112.9 CON Chan 76 N43°13.19' W71°34.53' 123° 3.4 NM to fld. 715/15W.  
 VOR unusable:  
 022°-032° byd 20 NM blo 8,000'  
 190°-210° byd 12 NM blo 4,000'  
 318°-326° byd 30 NM blo 12,000'  
 DME unusable:  
 022°-032° byd 20 NM blo 8,000'  
 082°-110° byd 30 NM blo 5,000'  
 190°-210° byd 12 NM blo 4,000'  
 290°-300° byd 30 NM blo 7,000'  
 318°-326° byd 30 NM blo 12,000'  
**EPSOM NDB (LOM)** 216 CO N43°07.13' W71°27.16' 353° 5.5 NM to fld. NDB unusable byd 20 NM.  
**ILS** 108.7 I-CON Rwy 35. Class IA. LOM EPSOM NDB. NDB unusable byd 20 NM.

**DEAN MEML** (See HAVERHILL on page 149)

**DILLANT/HOPKINS** (See KEENE on page 150)

**EPSOM** N43°07.13' W71°27.15' NOTAM FILE CON. NEW YORK  
L-32H, 33D  
**NDB (MHW/LOM)** 216 CO 353° 5.5 NM to Concord Muni. 355/16W.  
 NDB unusable:  
 Byd 20 NM

**ERROL** (ERR)(KERR) 1 NW UTC-(-4DT) N44°47.53' W71°09.87' MONTREAL  
 1248 TPA—2048(800) NOTAM FILE BGR  
**RWY 15-33:** 3600X60 (GRVL) 0.3% up SE  
**RWY 15:** Trees.  
**AIRPORT REMARKS:** Unattended. For arpt information and conditions, call 603-482-3320. Wildlife on and invof arpt. Regular construction vehicle tfc on roadway at Rwy 33 end. 1:1 clearance slope. Rwy 15-33: Rwy soft in spring. Lrg patches of grass on rwy.  
**AIRPORT MANAGER:** 603-616-8602  
**COMMUNICATIONS:** CTAF/UNICOM 122.8  
**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.  
 . . . . .  
**HELIPAD H1:** H61X61 (ASPH)  
**HELIPAD H1:** Trees.  
**HELIPORT REMARKS:** ACTIVATE helipad flood lgt and lighted windcone—CTAF.

**FITZY** N42°51.85' W71°31.73' NOTAM FILE MHT. NEW YORK  
**NDB (LOMW)** 209 MJ 060° 5.8 NM to Manchester Boston Rgnl. 234/15W.