

HAVERSTRAW HELIPORT (H43) 1 E UTC-5(-4DT) N41°12.66' W73°58.16'

NEW YORK

12 NOTAM FILE ISP

HELIPAD H1: H50X50 (ASPH) RWY LGTS(NSTD)

HELIPAD H1: Bldg.

SERVICE: FUEL JET A LGT For flood lgts call 914-429-1200.

NOISE: Noiae abatement; avoid residential area west of heliport.

HELIPORT REMARKS: Attended 1200-0000Z. For svc after hrs call 212-883-0999. Helipad H1 350' twrs 800' north of helipad. Helicopters descend to point on turf area west of pavement and taxi to paved location. Helipad H1 flood lgts

AIRPORT MANAGER: 845-429-1200

COMMUNICATIONS: CTAF/UNICOM 123.05

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2849.

HEBER AIRPARK (See GANSEVOORT on page 206)

HOLLANDS INTL FLD (See NEWFANE on page 231)

HORNELL MUNI (HTF)(KHTF) 3 N UTC-5(-4DT) N42°22.93' W77°40.93'

DETROIT

1219 B TPA—See Remarks NOTAM FILE BUF

H-10H, 11C, 12J, L-30I, 31E, 32F

RWY 18-36: H5000X75 (ASPH-GRVD) MIRL 0.5% up N

IAP

RWY 18: REIL. Thld dsplcd 500'. Hill.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 50'. Trees.

SERVICE: FUEL 100LL, JET A LGT ACTIVATE REIL Rwy 18-36 and MIRL Rwy 18-36—CTAF. REIL Rwy 18 OTS indef.

AIRPORT REMARKS: Attended 1300-2100Z. Frequent helicopter medivac ops, monitor CTAF. Rwy 36 PAPI unusable byd 5 degs right and left of centerline. TPA—2219(1000) daylight, 2419(1200) night. Cold temperature airport. Altitude correction required at or below -19C.

AIRPORT MANAGER: 607-968-9624

WEATHER DATA SOURCES: AWOS-3 118.475 (607) 324-9138.

COMMUNICATIONS: CTAF/UNICOM 122.7

CLEVELAND CENTER APP/DEP CON 124.325 or ctc Cleveland ARTCC at 440-774-0227.

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0227.

RADIO AIDS TO NAVIGATION: NOTAM FILE ELZ.

WELLSVILLE (DH) DME 115.85 ELZ Chan 105(Y) N42°05.38'

W77°59.97' 039° 22.5 NM to fld. 2298.

DME unusable:

170°-195° byd 25 NM

