VERMONT 339

WARREN-SUGARBUSH (ØB7) MONTRFAI 2 E UTC-5(-4DT) N44°07.04′ W72°49.62′

1470 NOTAM FILE BTV

RWY 04-22: H2575X30 (ASPH) S-8.5 0.5% up SW

RWY 04: Trees. Rgt tfc. RWY 22: Trees.

SERVICE: FUEL 100LL

AIRPORT REMARKS: Attended May-Oct 1400-2300Z‡. Arpt CLOSED Nov-Apr. Fuel self-serve only during hours airport is open. Extensive glider activity on arpt sfc to 18,000' dalgt hrs. Occasional aerobatic activity, arpt may be CLOSED during this activity; check NOTAMs. No line of sight between rwy ends. Touch and go ldgs not permitted. Grass areas not authorized for taxi, tkfs and ldgs without first checking UNICOM or management for fld conditions.

AIRPORT MANAGER: 802-496-2290

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc Burlington Apch at 802-657-4413, when Apch clsd ctc Boston ARTCC at 603-879-6859.

WFST DOVFR

DEERFIELD VALLEY RGNL (4V8) 1 SW UTC-5(-4DT) N42°55.63′ W72°51.94′

NEW YORK L-32G, 33C

1953 NOTAM FILE BTV

RWY 01-19: H2650X75 (ASPH) MIRL(NSTD) RWY 01. Trees

RWY 19: Trees

SERVICE: LGT Rwy 01-19 MIRL, NSTD alnmt.

AIRPORT REMARKS: Unattended. Fuel avbl 24 hrs with credit card. Ldg fee.

AIRPORT MANAGER: (802) 490-0775 COMMUNICATIONS: CTAF/UNICOM 122.8

BOSTON CENTER APP/DEP CON 123.75

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859. RADIO AIDS TO NAVIGATION: NOTAM FILE BTV.

CAMBRIDGE (L) (L) VORW/DME 115.0 CAM Chan 97 N42°59.66′

115° 21.5 NM to fld. 1490/14W.

W73°20.64′ DME unusable:

040°-130° blo 9,000′

VOR unusable: 128°-144°

161°-182°

195°-205°

Golf Course ß €3 €3 €3 €3 a Œ €3 ß €3 €3 **43** ß €3 €3 ß €3 €3 Œ Œ €3 €3 €3 €3 €3 €3 €3 C3 €3 €3 **(3** €3 €3 €3 €3 €3 **43** €3 3 **(3** €3 €3 Ø €3 €3

WILLIAM H MORSE STATE (See BENNINGTON on page 330)