

WEIRWOOD

CAMPBELL FLD (9VG) 1 W UTC-5(-4DT) N37°27.51' W75°52.73'

WASHINGTON

- 40 NOTAM FILE DCA
- RWY 03-21:** 3000X100 (TURF)
- RWY 03:** P-line.
- RWY 21:** Road.
- RWY 14-32:** 1455X140 (TURF)
- RWY 14:** Road.
- RWY 32:** Trees.

AIRPORT REMARKS: Attended Mar-Nov dalgt hours. Be alert: 60' P-lines located 300' southwest off the AER 03.
AIRPORT MANAGER: 914-772-6242
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Norfolk Apch at 757-464-0757.

WEST POINT

MIDDLE PENINSULA RGNL (FYJ)(KFYJ) 2 SE UTC-5(-4DT) N37°31.28' W76°45.77'

WASHINGTON
 H-10H, 12I, L-34E, 36H
 IAP

- 20 B TPA—See Remarks NOTAM FILE FYJ
- RWY 10-28:** H5000X75 (ASPH) S-30, D-50, 2D-85 MIRL
- RWY 10:** REIL. PAPI(P2L)—GA 3.5° TCH 53'. Tree.
- RWY 28:** REIL. PAPI(P2L)—GA 3.5° TCH 53'. Trees.

SERVICE: S4 FUEL 100LL, JET A+ LGT REIL Rwy 10 and Rwy 28, MIRL Rwy 10-28 opr SS-SR. Drg dalgt hrs, PCL avbl upon req, ctc amgr. ACTVT REIL Rwy 10 and Rwy 28, MIRL Rwy 10-28—CTAF.

AIRPORT REMARKS: Attended 1300-2200Z±. Full and self-serve fuel avbl. Parachute Jumping weekends only. Deer on and invof arpt. TPA—820(800) light acft, 1520(1500) heavy acft. Rotor-wing and tiltrotor acft fly tfc pats south of Rwy 10-28 at 800' AGL or abv. Rwy 10 non-std marking placement.


AIRPORT MANAGER: 804-785-9725
WEATHER DATA SOURCES: AWOS-3 132.825 (804) 785-2307.
COMMUNICATIONS: CTAF/UNICOM 123.0

® POTOMAC APP/DEP CON 126.75
CLEARANCE DELIVERY PHONE: For CD ctc Norfolk Apch at 757-464-0757.

RADIO AIDS TO NAVIGATION: NOTAM FILE DCA.
HARCUM (L) (L) VORTACW 108.8 HCM Chan 25 N37°26.92'
 W76°42.68' 338° 5.0 NM to fld. 8/7W.

VOR unusable:
 056°-095° blo 2,000'
 174°
 275°-300° blo 2,000'

LOC/DME 109.55 I-FYJ Chan 32(Y) Rwy 10.



WILLIAM M TUCK (See SOUTH BOSTON on page 382)