OREGON

)) 15 SW UTC- A NOTAM FILE H		2°57.04′ \$ H–18
		S-50, D-70, 2D-11		I
		3.0° TCH 49'. RVR	I-T	
	PAPI(P4L)—GA 3.0			
			PCN 20 F/C/X/T MIRL	
		39'. Road. Rgt tfc.		
RWY 20: PAPI(P	4L)—GA 3.0° TCH	38´. Tree.		
RWY 13L-31R: H36	00X60 (ASPH) S-	-28 PCN 10 F/D/Y/T	i Mirl	
RWY 13L: PAPI(P4L)—GA 3.0° TCH	127′.		
RWY 31R: PAPI(P4L)—GA 3.0° TCH	126´. Rgt tfc.		
LAND AND HOLD-SH	ORT OPERATIONS			
LDG RWY	HOLD–SHORT PO	INT AVB	L LDG DIST	
RWY 13R	02-20	492	22	
SERVICE: S4 FUE	L 100LL, JET A C	JX 1, 2, 4 LGT Whe	n twr clsd ACTVT MALSR Rwy 1	3R; PAPI Rwy 02 and PAPI
			d R of rwy cntrln. Rwy 31R PAP	
rwy cntrln.	,	,	, ,	, 3
,	procedures in effect	call 503-460-410	0 or 800–938–6647. Noise sens	itive areas border arpt west.
	·		oid low level over fits of resident	
,		ouraged 0600–1400		
0	0	0	L clsd to touch and go ldgs betw	reen 0600–14007± Re alert
		-	west during dalgt hrs Mar–Oct. 1	
			ble from twr. Rwy 02–20 has 15	
			ds at both ends. Be alert, extv hel	
-				
			6) avbl, 2 hr advance ntc rqr Mor	
			ertified maximum gross ldg weigh	
			single engine, \$175 twin engin	
			Notification (ADCUS) avbl, advar	
		an induces—intensi	ve Flight Training Advisory. See	special notices—Arrival Aler
AIRPORT MANAGER:		F 4014		
	RCES: ASOS (503) 61			
		.65 UNICOM 122.95		
		W) 118.1 284.6 (HIGH)	
	1400-0600Z‡) GND			
			and Apch at 503-493-7545.	
	.,	other times CLASS	Ε.	
VOR TEST FACILITY (/OT) 115.2			
RADIO AIDS TO NAVI	GATION: NOTAM FILI	E MMV.		
NEWBERG (VH) (H) VORW/DME 117.4	UBG Chan 12	1 N45°21.19' W122°58.69'	345° 11.4 NM to fld.
1443/21E.				
VOR unusable				
095°-105°	byd 40 NM			
	byd 40 NM blo 7,8	00 <i>′</i>		
106°-120°				
135°-328°		00/		
	byd 40 NM blo 5,0	00		
329°–346°				
2470 0000			02.75′ 127° 6.6 NM to fld. 2	
347°-080°		1 F037 83' \N/1 330r		
BANKS NDB (MH)	W)356 PND N			
BANKS NDB (MH) ILS 110.7 I–I	W)356 PND N		red when ATCT clsd. Localizer un	
BANKS NDB (MH) ILS 110.7 I-I course.	V)356 PND N HIO Rwy13R. C		red when ATCT clsd. Localizer u	