

CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE POB.

(H) TACAN Chan 85 POB (113.8) N35°10.11' W79°01.17' at fld. 205/7W.

TACAN AZIMUTH unusable:

- 006°-089° byd 25 blo 4,000'
- 090°-092° byd 15 NM
- 093°-143° byd 25 NM blo 4,000'
- 144°-148° byd 18 NM
- 149°-278° byd 25 NM blo 4,000'
- 306°-311° byd 25 NM
- 312°-335° byd 25 NM blo 4,000'
- 336°-338° byd 25 NM
- 339°-350° byd 25 NM blo 4,000'
- 351°-355° byd 12 NM
- 356°-005° byd 25 NM

DME unusable:

- 006°-089° byd 25 NM blo 4,000'
- 090°-092° byd 15 NM
- 093°-143° byd 25 NM blo 4,000'
- 144°-148° byd 18 NM
- 149°-278° byd 25 NM blo 4,000'
- 152°-155° byd 25 NM
- 196°-209° byd 25 NM
- 245°-251° byd 25 NM
- 312°-335° byd 25 NM blo 4,000'
- 339°-350° byd 25 NM blo 4,000'
- 351°-355° byd 12 NM

ILS 110.9 I-POB Rwy 23. ATC protects FAA defined ILS critical zone.

RAEFORD

P K AIRPARK (5W4) 3 NE UTC-5(-4DT) N35°01.19' W79°11.46'

304 B NOTAM FILE RDU

RWY 04-22: H3402X60 (ASPH) S-30 MIRL 0.4% up NE

RWY 04: Trees.

RWY 22: Trees. Rgt tfc.

SERVICE: FUEL 100LL, JET A+

AIRPORT REMARKS: Attended 1330Z±-dusk. Parachute Jumping. After hrs svc 910-578-4401. Low flying mil acft in area, arpt located within a MOA. Caution, do not overfly airport due to PJA. Frequent parachute activity to target 300' SE of terminal apron. Fly 1 mile down wind leg to prevent conflicts with parachute jumping activity (Drop Zone SE from rwy).

AIRPORT MANAGER: (910) 904-0000

COMMUNICATIONS: CTAF/UNICOM 123.0

Ⓡ FAYETTEVILLE APP/DEP CON 127.8

CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at 703-771-3587.

RADIO AIDS TO NAVIGATION: NOTAM FILE FAY.

FAYETTEVILLE (L) VOR/DME 114.85 FAY Chan 95(Y)
N34°59.13' W78°52.50' 282° 15.7 NM to fld. 187/4W.

VOR unusable:
058°-068° blo 4,000'

DME unusable:
090°-100°

COMM/NAV/WEATHER REMARKS: Monitor frequency 123.5 for parachute jumping activity. Acft in vicinity monitor 123.5.

CHARLOTTE

L-35A, 36F

IAP

