

WESTERN CAROLINA RGNL (See ANDREWS on page 293)

WHITEVILLE**COLUMBUS CO MUNI** (CPC)(KCPC) 3 S UTC-5(-4DT) N34°16.37' W78°42.90'

99 B NOTAM FILE CPC

RWY 06-24: H5500X75 (ASPH) S-45, D-60 MIRL 0.5% up SW**RWY 06:** REIL. PAPI(P2L)—GA 3.0° TCH 40'. Trees.**RWY 24:** REIL. PAPI(P2L)—GA 3.25° TCH 42'. Trees.**SERVICE:** FUEL 100LL, JET A1+ LGT Actvt REIL Rwy 06 & 24; MIRL

Rwy 06-24—CTAF. PAPI Rwy 06 & 24 on consly.

AIRPORT REMARKS: Attended Mon-Sat 1300-2300Z‡, Sun 1400-2300Z‡.

Deer and turkeys on and in/ovf arpt. Fuel 24 hr credit card svc avbl. For emergency service after hrs call 910-654-3389 or 910-625-5489.

Arpt unatndd Easter Sunday, 4th July, Thanksgiving Day, Christmas Eve and Christmas Day. No off-pavement ldg allowed.

AIRPORT MANAGER: 910-642-6187**WEATHER DATA SOURCES:** AWOS-3 118.375 (910) 642-7508.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **MYRTLE BEACH APP/DEP CON** 119.2 (1100-0400Z‡)Ⓡ **JACKSONVILLE CENTER APP/DEP CON** 134.375 (0400-1100Z‡)**CLEARANCE DELIVERY PHONE:** For CD ctc Myrtle Beach Apch at 843-477-2727 or 843-477-2704, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.**RADIO AIDS TO NAVIGATION:** NOTAM FILE FLO.**FLORENCE (H) (H) VORTACW** 115.2 FLO Chan 99 N34°13.98' W79°39.43' 090° 46.9 NM to fld. 104/3W.

TACAN AZIMUTH unusable:

200°-025° byd 30 NM blo 4,000'

VOR unusable:

089°-125° byd 30 NM blo 3,000'

126°-194° byd 10 NM

195°-223° byd 10 NM blo 4,000'

219°-229° byd 25 NM blo 13,000'


345°-360° byd 10 NM

DME unusable:

200°-025° byd 30 NM blo 4,000'

CAMP NDB (MHW) 227 CPC N34°16.39' W78°42.72' at fld. 79/7W. NOTAM FILE CPC. NDB unmonitored

Mon-Sat 2300-1300Z‡ and Sun 2300-1400Z‡.

CHARLOTTE
H-9C, 12H, L-35A
IAP**WHITFIELD FARMS** (See HURDLE MILLS on page 314)**WILKES CO** (See NORTH WILKESBORO on page 332)