92 ALASKA

DEERING (DEE)(PADE) 2 SW UTC-9(-8DT) N66°04.15′ W162°46.02′

30 B NOTAM FILE DEE

RWY 03-21: 3320X75 (GRVL) MIRL

RWY 03: REIL. PAPI(P4R)—GA 3.0° TCH 25'.

RWY 12–30: 2660X75 (GRVL) MIRL 0.4% up NW

SERVICE: LGT ACTIVATE MIRL Rwy 03–21 and Rwy 12–30; REIL Rwy 03 and PAPI Rwy 03 —CTAF. ACTIVATE rotating bcn —CTAF.

O3 and PAPI Rwy O3 —CTAF. ACTIVATE rotating bon —CTAF. AIRPORT REMARKS: Unattended. Migratory birds as well as musk oxen and other large animals on and invof of rwys. Rwy cond not monitored, recommend visual inspection prior to Idg. Cold temperature airport. Altitude correction required at or below —39C. Rwy O3—21 plowed in winter. Windsock missing at Rwy 12. Rwy O3—21 NSTD markings, marked with Igts and plastic markers. Rwy 12—30 NSTD markings, marked with Igts and plastic markers.

AIRPORT MANAGER: 907-442-3147

WEATHER DATA SOURCES: ASOS 135.5 (907) 363-2102. (WX CAM)

COMMUNICATIONS: CTAF 122.9

DEERING RCO 122.25 (KOTZEBUE RADIO) Anchorage center app/dep con 119.2 263.0

RADIO AIDS TO NAVIGATION: NOTAM FILE OTZ.

KOTZEBUE (H) (H) VORW/DME 115.7 OTZ Chan 104 N66°53.14′ W162°32.40′ 171° 49.5 NM to fld. 121/15E.

COMM/NAV/WEATHER REMARKS: For a LC to Kotzebue FSS dial 907–442–3310. For a toll free call to Kotzebue FSS dial 1–800–478–7460. For a toll free call to Fairbanks FSS dial 1–866–248–6516.

DELTA DAVES (See DELTA JUNCTION on page 92)

DELTA JUNCTION

ALL WEST (AK77) PVT 11 E UTC-9(-8DT) N63°56.49′ W145°25.33′ 1275 NOTAM FILE Not insp.

ANCHORAGE H-1B. L-1A. 3B. 3E

NOME

I _4H

IAP

RWY 09-27: 5500X75 (TURF-GRVL)
AIRPORT REMARKS: Unattended.
AIRPORT MANAGER: 907-895-9800

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

DELTA DAVES (AA22) PVT 7 NW UTC-9(-8DT) N64°07.69′ W145°48.51′

FAIRBANKS

1049 NOTAM FILE Not insp.

RWY 06-24: 1800X100 (TURF-DIRT)

RWY 06: Trees.

AIRPORT REMARKS: Unattended.
AIRPORT MANAGER: 907-895-4887

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

DELTA JUNCTION (D66) 1 N UTC-9(-8DT) N64°03.01′ W145°43.35′

FAIRBANKS

1150 NOTAM FILE FAI RWY 07-25: 2500X60 (GRVL)

RWY 07: Trees.

RWY 25: Trees. Rgt tfc.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to use. Rwy within 5 miles of Allen Army arfld. Rwy 07 p-line W of rwy marked with orange balls. Clnc slope to p-line 33:1. 335' lgtd twr 1 mi S of arpt. Arpt and electricity usage fees apply. Ctc arpt mgmt. Rwy 07–25 edges marked with reflective cones. Transient parking on East end, South side of Rwy 07. Personnel and eqpt may be working on the rwy at any time.

AIRPORT MANAGER: 907-460-6688

 ${\color{red}\textbf{COMMUNICATIONS: CTAF}\ 122.9}$

SUAIS 125.3 126.3 (1-800-758-8723).

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1–866–248–6516.

171° 49.5 NM
From Kotzebue
"OTZ" VOR/DME
Tundra