

WILMINGTON

CLINTON FLD (I66) 4 NW UTC-5(-4DT) N39°30.15' W83°51.80' CINCINNATI
1033 B NOTAM FILE DAY L-27E
RWY 03-21: H3579X60 (ASPH) S-12.5 MIRL 0.3% up NE IAP
RWY 03: PAPI(P2L)—GA 3.0° TCH 36'. Trees.
RWY 21: PAPI(P2L)—GA 3.75° TCH 20'. Trees.
SERVICE: **FUEL** 100LL **LGT** Actvt MIRL Rwy 03-21—CTAF. PAPI Rwy 03 and 21 opr consly. Rwy 21 PAPI unusbl byd 5° right of cntrln.
AIRPORT REMARKS: Unattended. Deer and birds on and invof arpt. 100LL avbl self svc via credit card only.
AIRPORT MANAGER: 937-382-4638
WEATHER DATA SOURCES: AWOS-3 124.175 (937) 382-1376.
COMMUNICATIONS: CTAF/UNICOM 122.725
® **COLUMBUS APP/DEP CON** 118.85
CLEARANCE DELIVERY PHONE: For CD ctc Columbus Apch at 614-338-8537.
RADIO AIDS TO NAVIGATION: NOTAM FILE ILN.
MIDWEST (T) (T) VORW/DME 112.9 MXQ Chan 76 N39°25.78' W83°48.07' 331° 5.2 NM to fld. 1052/4W.
VOR unusable:
051°-200°
201°-244° byd 10 NM blo 10,000'
245°-255° byd 20 NM blo 10,000'
256°-297° byd 18 NM blo 10,000'
298°-359°
300°-050° wi 3 NM
360°-022° blo 6,000'
360°-022° byd 18 NM blo 10,000'
DME unusable:
003°-024°
282°-302° byd 18 NM blo 4,000'
303°-309°
310°-320° byd 18 NM blo 6,000'
335°-340° byd 18 NM blo 6,000'

HOLLISTER FLD (2B6) 5 E UTC-5(-4DT) N39°26.25' W83°42.50' CINCINNATI
1090 TPA—See Remarks NOTAM FILE DAY
RWY 05-23: 3203X80 (TURF)
RWY 05: Thld dsplcd 92'.
RWY 23: Thld dsplcd 565'. Road.
RWY 13-31: 2670X80 (TURF)
RWY 13: Thld dsplcd 250'. Fence.
RWY 31: Thld dsplcd 732'. Fence.
SERVICE: **FUEL** , UL94
AIRPORT REMARKS: Attended dalgt hrs. Pheasants released for hunting on north side of Rwy 05-23 Sep-Apr. Model acft rdo ctl area south of Rwy 05-23. Call for rwy conds prior to ldg. Rwy 13-31 clsd indefly. Rwy ends 05 and 23 not vsb at TPA. Rwy ends 05 and 23: rwy and dthr mkd with white tires at 600 ft intvls. Tie transient storage: ropes not prvdd.
AIRPORT MANAGER: 937-603-2636
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Columbus Apch at 614-338-8537.
