

GRANT MUNI (GGF)(KGGF) 2 N UTC-7 (-6DT) N40°52.24' W101°44.03'

1385 B NOTAM FILE OLU

RWY 15-33: H4797X60 (CONC) S-30, D-30 MIRL**SERVICE:** FUEL 100LL LGT ACTVT MIRL Rwy 15-33—CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1500-0000Z. Self svc H24 via credit card. FBO on arpt Mon-Fri 1500-0000Z, flt instrn avbl. Ctc 308-491-9001.**AIRPORT MANAGER:** (308) 352-2100**WEATHER DATA SOURCES:** AWOS-3PT 118.025 (308) 352-4689. SAWRS.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **DENVER CENTER APP/DEP CON** 132.7**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.**RADIO AIDS TO NAVIGATION:** NOTAM FILE OGA.**SEARLE (T) (T) VORW/DME** 110.2 SAE Chan 39 N41°07.15' W101°46.56' 166° 15.0 NM to fld. 3256/7E.

DME portion unusable:


274°-034° byd 15 NM

NORTH PLATTE (L) (L) VORW/DME 117.4 LBF Chan 121 N41°02.92'

W100°44.83' 246° 46.1 NM to fld. 3069/11E. NOTAM FILE LBF.

NDB (MHW) 359 GGF N40°52.26' W101°43.83' at fld.

3412/9E. NOTAM FILE OLU.


COMM/NAV/WEATHER REMARKS: SAWRS avbl for Part 135 ops; Call 308-352-2223 at least 24 hrs in advance.**HARLAN CO LAKE SPB** (See ALMA on page 290)**HARTINGTON MUNI/BUD BECKER FLD** (ØB4) 2 SE UTC-6(-5DT) N42°36.19' W97°15.21'

1388 B NOTAM FILE OLU

RWY 13-31: H3950X60 (CONC) MIRL 0.3% up SE**RWY 13:** PAPI(P2L)—GA 3.5° TCH 46'.**RWY 31:** PAPI(P2L)—GA 3.25° TCH 40'. Thld dsplcd 400'.**RWY 03-21:** 2150X125 (TURF) 0.6% up SW**SERVICE:** S4 FUEL 100LL LGT ACTIVATE MIRL Rwy 13-31, PAPI Rwy 13 and Rwy 31—CTAF.**AIRPORT REMARKS:** Attended continuously. For fuel call 402-254-7316 or 402-841-0659. Rwy 03-21 not plowed during winter months.**AIRPORT MANAGER:** 402-841-0659**COMMUNICATIONS:** CTAF 122.9® **MINNEAPOLIS CENTER APP/DEP CON** 125.025**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE YKN.**YANKTON (L) DME** 111.4 YKN Chan 51 N42°55.10' W97°23.10' 163° 19.8 NM to fld. 1301.

DME unusable:

249°-264° byd 24 NM blo 2,800'



OMAHA

L-12H

IAP