

CROSBY MUNI (D50) 1 N UTC-6(-5DT) N48°55.70' W103°17.85'

1953 B NOTAM FILE GFK

RWY 13-31: H3800X75 (ASPH) S-12.5 MIRL**RWY 13:** PAPI(P2L)—GA 3.0° TCH 33'.**RWY 31:** PAPI(P2L)—GA 3.0° TCH 33'.**RWY 03-21:** 2680X100 (TURF) 0.3% up SW

SERVICE: FUEL 100LL LGT PAPI Rwy 13 and Rwy 31 oper dusk-0700Z†. MIRL Rwy 13-31 preset on low intst dusk-0700Z†; to incr intst ACTVT—CTAF. Aft 0700Z† ACTVT MIRL Rwy 13-31; PAPI Rwy 13 and Rwy 31—CTAF.


AIRPORT REMARKS: Unattended. Self svc fuel avbl H24 via credit card. Rwy 03-21 CLOSED winter months due to lack of snow removal. Deer and birds on and invof arpt. +250' tower 4000' south of arpt.

AIRPORT MANAGER: 701-570-0944**WEATHER DATA SOURCES:** AWOS-3 118.025 (701) 965-6732.**COMMUNICATIONS:** CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE ISN.**WILLISTON (VL) (DH) VORW/DME** 116.3 ISN Chan 110

N48°15.20' W103°45.04' 016° 44.4 NM to fld. 2365/8E.


BILLINGS
 L-13E, 14F
 IAP
DEERING N48°24.92' W101°21.97' NOTAM FILE MIB.**(H) TACAN** 114.9 MIB Chan 96 1654/7E.

No NOTAM MP: 1530-1730Z† Wed (1500/3+1)

TACAN AZ unusable:

294°-304° byd 13 NM blo 5,000'

294°-304° byd 21 NM

DME unusable:

294°-304° byd 13 NM blo 5,000'

294°-304° byd 21 NM

BILLINGS
 H-2H, L-14F