

**BIRD CITY****BRESSLER FLD** (5K0) 1 SW UTC-6(-5DT) N39°44.65' W101°33.39'

WICHITA

3489 B NOTAM FILE ICT

**RWY 08-26:** 3460X70 (TURF)**RWY 08:** Road. Rgt t/c.**RWY 26:** Road.**RWY 17-35:** 2270X75 (TURF)**RWY 17:** Road.**RWY 35:** Road.**SERVICE:** LGT Rotating bcn OTS indef.**AIRPORT REMARKS:** Attended Apr-Sep dalgt hours, Oct-Mar unattended. During Oct-Mar call 785-734-2631 for arpt conditions. East of Rwy 08-26 has one third rough sfc.**AIRPORT MANAGER:** 785-734-2631**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.**BLOSSER MUNI** (See CONCORDIA on page 93)**BORTH FLD** (See MEADE on page 121)**BRESSLER FLD** (See BIRD CITY on page 89)**BUCKLIN** (8K0) 1 SW UTC-6(-5DT) N37°32.74' W99°38.53'

WICHITA

2418 B NOTAM FILE ICT

**RWY 18-36:** 2560X150 (TURF) 0.6% up N**RWY 18:** Pole.**RWY 36:** Road.**AIRPORT REMARKS:** Unattended.**AIRPORT MANAGER:** 620-826-5519**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.**BURLINGTON****COFFEY CO** (UKL)(KUKL) 7 N UTC-6(-5DT) N38°18.15' W95°43.50'

KANSAS CITY

1174 B NOTAM FILE ICT

H-5C, L-101, 15E

**RWY 18-36:** H5500X75 (CONC) S-39, D-50 PCN 13 R/D/W/T

IAP

MIRL

**RWY 18:** REIL. PAPI(P4L)—GA 3.0° TCH 40'.**RWY 36:** REIL. PAPI(P4L)—GA 3.0° TCH 43'.**SERVICE:** S4 FUEL 100LL, JET A LGT MIRL Rwy 18-36 opr dusk-0400Z†. After 0400Z† ACTIVATE PAPI Rwy 18 and Rwy 36, MIRL Rwy 18-36—CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1400-0000Z†, Sat-Sun 1400-2300Z†. Arpt unattended Thanksgiving and Christmas.

Wildlife on and invof arpt. Ultralight activity on and invof arpt.

**AIRPORT MANAGER:** 620-364-5346**WEATHER DATA SOURCES:** AWOS-3PT 121.125 (620) 364-2435.**COMMUNICATIONS:** CTAF/UNICOM 123.0

® KANSAS CITY CENTER APP/DEP CON 127.725


**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.**RADIO AIDS TO NAVIGATION:** NOTAM FILE EMP.**EMPORIA (L) (H) VORTACW** 112.8 EMP Chan 75

N38°17.47' W96°08.29' 080° 19.5 NM to fld.

1222/8E.

TACAN unusable:

205°-245° byd 40 NM

**BUTLER AIRPARK** (See ROSE HILL on page 134)