

MOUNT HOLLY

SOUTH JERSEY RGNL (VAY)(KWAY) 4 SW UTC-5(-4DT) N39°56.57' W74°50.75'

WASHINGTON

53 B TPA—853(800) NOTAM FILE VAY

L-346, A

RWY 08-26: H3881X50 (ASPH) S-30 MIRL

IAP

RWY 08: REIL. PAPI(P2R)—GA 3.25° TCH 45'. Tree.

RWY 26: REIL. PAPI(P2R)—GA 3.0° TCH 40'. Tree. Rgt tfc.

SERVICE: S4 **FUEL** 100LL, JET A **LGT** ACTIVATE MIRL Rwy 08-26 and REIL Rwy 08 and Rwy 26—123.3.

AIRPORT REMARKS: Attended Apr-Oct 1300-0100Z†, Nov-Mar 1300-2300Z†. Arpt unatndd Thanksgiving & Christmas Day. Christmas & Thanksgiving eve hrs 1300-1700Z. New Years Day hrs 1600-2300Z. Jet A fuel avbl 24 hr self svc with credit card or truck during attended hrs. Deer on and invof arpt. Helicopter tkfs and ldgs restricted to Rwy 08-26 only. Balls marking p-lines on apch to Rwy 08 faded. Trees along sides of rwy primarily northwest. Avoid overflying housing area WNW of arpt blo 300' when in the traffic pattern for Rwy 08. Parallel twy nstd with 18' asphalt. Rwy 08 VGSI and descent angles not coincident.

AIRPORT MANAGER: 609-267-3131

WEATHER DATA SOURCES: ASOS 119.325 (609) 267-1176.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **MC GUIRE APP/DEP CON** 126.475

CLEARANCE DELIVERY PHONE: For CD ctc: Mc Guire Apch at 609-754-2767.

RADIO AIDS TO NAVIGATION: NOTAM FILE MIV.

ROBBINSVILLE (H) (H) VORTACW 113.8 RBV Chan 85 N40°12.14' W74°29.70' 236° 22.4 NM to fld. 248/10W.

TACAN AZIMUTH unusable:

105°-115° byd 30 NM

DME unusable:

075°-115° byd 25 NM

130°-160° byd 30 NM blo 4,000'

