

ELKINS/RANDOLPH CO (JENNINGS RANDOLPH FLD) (EKN)(KEKN) 2 S UTC-5(-4DT) N38°53.37' CINCINNATI
W79°51.43' L-29C
1987 B TPA-3000(1013) NOTAM FILE EKN
RWY 14-32: H4544X140 (ASPH) S-10 1.0% up NW
RWY 14: Tree.
RWY 32: Thld dsplcd 1390'. Trees.
RWY 05-23: H4501X75 (ASPH) S-28, D-35, 2D-56 MIRL
0.6% up SW
RWY 05: Thld dsplcd 154'. Trees.
RWY 23: REIL. PAPI(P2L)-GA 5.0° TCH 45'. Antenna.
SERVICE: FUEL 100LL, JET A LGT Actvt MIRL Rwy 05-23 & REIL Rwy
23-122.9. Rwy 23 omni-directional REIL. PAPI Rwy 23 non-std 5
deg glide angle.
AIRPORT REMARKS: Attended 1330-2200Z†. Rwy 14-32 CLOSED
dusk-dawn. Deer on and invof arpt. Uncontrolled vehicles Rwy 32
crossing thr. For aftr hrs serv call amgr during bus hrs. All fueling 24 hr
self service. Rwy 05-23 & Rwy 14-32 2-12 inch deep drainage
structures on paved shoulders. Rwy 14-32 mkgd faded. Rwy 23, 68 ft
athletic fld lgts, 550 ft south of rwy centerline. Cold temperature airport.
Altitude correction required at or below -20C.
AIRPORT MANAGER: 304-636-2726
WEATHER DATA SOURCES: ASOS 119.275 (304) 636-5603.
COMMUNICATIONS: CTAF 123.6
Ⓡ CLARKSBURG APP/DEP CON 121.15 (1200-0400Z†)
Ⓡ WASHINGTON CENTER APP/DEP CON 128.6 (0400-1200Z†)
CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Washington ARTCC at 703-771-3587.
AIRSPACE: CLASS E svc 1200-0400Z†; other times CLASS G.
RADIO AIDS TO NAVIGATION: NOTAM FILE EKN.

(L) **VORTACW** 114.2 EKN Chan 89 N38°54.87' W80°05.96' 104° 11.4 NM to fld. 2160/7W.


TACAN AZIMUTH unusable:
081°-148° byd 32 NM blo 9,000'
149°-193°

273°-039° byd 12 NM blo 6,000'
DME unusable:
081°-148° byd 32 NM blo 9,000'
149°-193°

273°-039° byd 12 NM blo 6,000'
RANDOLPH COUNTY NDB (HW) 284 RQY N38°53.64' W79°51.56' at fld. 1938/7W.

NDB unusable:
018°-084° byd 10 NM
085°-017° byd 15 NM

LDA/DME 109.9 I-OUW Chan 36 Rwy 00X. LDA is circling apch only. LOC unusable byd 6.0 NM blw 4,500'. DME
portion unusable byd 6.0 NM blw 4,500'.



ELKINS N38°54.87' W80°05.96' NOTAM FILE EKN. CINCINNATI

(L) **VORTACW** 114.2 EKN Chan 89 104° 11.4 NM to Elkins/Randolph Co (Jennings Randolph Fld). H-10H, 12H, L-29C
2160/7W.

TACAN AZIMUTH unusable:
081°-148° byd 32 NM blo 9,000'
149°-193°

273°-039° byd 12 NM blo 6,000'
DME unusable:
081°-148° byd 32 NM blo 9,000'
149°-193°

273°-039° byd 12 NM blo 6,000'