

NAPLES

BRANDY POND SPB (5ME) 1 SE UTC-5(-4DT) N43°57.23' W70°35.25' NEW YORK
268 NOTAM FILE BGR
WATERWAY 17W-35W: 7200X600 (WATER)
SERVICE: S2 FUEL MOGAS
SEAPLANE REMARKS: Attended May-Oct Mon-Fri 1300-2200Z±, Nov-Apr unattended. Follow channel markers to avoid shallow water, turn west after 3rd marker to dock. Jun-Aug heavy boat tfc on lake.
AIRPORT MANAGER: (207) 693-6254
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.

LONG LAKE SPB (76B) 1 NE UTC-5(-4DT) N43°59.22' W70°37.11' NEW YORK
268 NOTAM FILE BGR
WATERWAY 16W-34W: 15000X3960 (WATER)
SERVICE: FUEL 100LL
SEAPLANE REMARKS: Attended Jun-Oct 1400Z±-dusk. June-Oct Sun unatndd. 100LL emerg fuel only. Wind sock at dock.
AIRPORT MANAGER: 207-232-2594
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.
COMM/NAV/WEATHER REMARKS: Monitor CTAF within 5 NM of Naples.

NEWTON FLD (See JACKMAN on page 72)

NORCROSS(MILLINOCKET)

BUCKHORN CAMPS SPB (78B) 0 NE UTC-5(-4DT) N45°39.25' W68°56.97' HALIFAX
500 NOTAM FILE BGR
WATERWAY NW-SE: 4000X500 (WATER)
WATERWAY NW: Trees.
WATERWAY SE: Trees.
WATERWAY E-W: 3000X500 (WATER)
WATERWAY E: Trees.
WATERWAY W: Trees.
SEAPLANE REMARKS: Attended continuously. Many shallow rocky areas during low water conditions in middle of lake. Many shallow rocky areas around the docking area. Shallow areas with rocks near island west of the NW/SE sea lane.
AIRPORT MANAGER: 207-723-1548
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.