


SEATTLE PAINE FLD INTL (See EVERETT on page 238)

SEKIU (11S) 0 NW UTC-8(-7DT) N48°15.97' W124°18.84'
355 B NOTAM FILE SEA
RWY 08-26: H2997X50 (ASPH) LIRL
RWY 08: Thld dsplcd 900'. Trees.
RWY 26: NSTD—GA 4.0° TCH 35'. Tree.
SERVICE: LGT Rwy 26 Nstd 2 box VASI left side ngts only.
AIRPORT REMARKS: Unattended. Deer on and invof arpt Sep-Mar. High ridge along N side of rwy. Turbulence on E end apch over water. Difficult apch when wind from N. Rwy 08-26 wdspr alligator and block cracking. Bathroom lock combination is 2608.
AIRPORT MANAGER: 360-417-3437
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

SEATTLE

SEQUIM VALLEY (W28) 4 NW UTC-8(-7DT) N48°05.88' W123°11.28'
151 B NOTAM FILE SEA
RWY 09-27: H3508X40 (ASPH) LIRL
RWY 09: Trees. Rgt tfc.
RWY 27: Trees.
SERVICE: FUEL 100LL
AIRPORT REMARKS: Unattended. Self svc fuel avbl 24 hrs. Wildlife on and invof arpt. Rwy 09-27 has 2 inch shoulder dropoff. Ldg fee.
AIRPORT MANAGER: 360-670-3083
COMMUNICATIONS: CTAF/UNICOM 122.7
CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.
RADIO AIDS TO NAVIGATION: NOTAM FILE SEA.
TATOOSH (VH) (H) VORTACW 112.2 TOU Chan 59 N48°17.99' W124°37.62' 079° 59.0 NM to fld. 1650/22E.

VOR unusable:
020°-025° byd 40 NM
085°-090° byd 40 NM
091°-101° byd 40 NM blo 15,000'
091°-101° byd 58 NM
103°-109° byd 40 NM
356°-360° byd 40 NM



SEATTLE
L-1E

SHADY ACRES (See SPANAWAY on page 280)