

AMERICAN SAMOA

OFU ISLAND

OFU (ZØ8)(NSAS) 1 SE UTC-11 S14°11.06' W169°40.21' HAWAIIAN-MARIANA

12.2 Class III, ARFF Index A NOTAM FILE HNL

RWY 08-26: H1980X60 (CONC-WC) S-12.5 D-12.5 PCN 7 R/C/Z/U

RWY 08: Tree.

RWY 26: Tree.

AIRPORT REMARKS: Attended during scheduled flights only. To land ctc airport manager Pago Pago Intl, call 699-9101. Brush and trees Rwy 08-26 along ldg area encroach into imaginary sfc defined by FAR PART 77. Boulders/rocks adjacent to Rwy 08 apch. 400' MSL powerlines between OFU and Olosega Islands. Numerous high voltage transformer boxes 3' high along north side of rwy. Numerous hydrants 4+ ' along north side of rwy.

AIRPORT MANAGER: (684) 699-9101

COMMUNICATIONS: CTAF/UNICOM 122.95

COMM/NAV/WEATHER REMARKS: For arpt information ctc New Zealand NOTAM and briefing office (643) 358-1688/FAX (643) 358-9192.

TAU ISLAND

FITUTUA (FAQ)(NSFQ) 0 N UTC-11 S14°12.97' W169°25.41' HAWAIIAN-MARIANA

110.4 B Class III, ARFF Index A NOTAM FILE HNL

RWY 12-30: H3200X75 (CONC-GRVD) S-12.5 PCN 7 R/C/Z/U MIRL

RWY 12: REIL. PAPI(P2L)—GA 3.0° TCH 39'.

RWY 30: REIL. PAPI(P2L)—GA 3.0° TCH 39'.

SERVICE: LGT ACTVT REIL Rwys 12 and 30; PAPI Rwys 12 and 30; MIRL Rwy 12-30—CTAF (122.9). Rwy 12 and Rwy 30 PAPI OTS indef.

AIRPORT REMARKS: Attended 1600-0400Z.

AIRPORT MANAGER: (684) 699-9101

COMMUNICATIONS: CTAF 122.9

COMM/NAV/WEATHER REMARKS: For arpt information ctc New Zealand NOTAM and briefing office (643) 358-1688. FSS: NEW ZEALAND, 643-358-1688/FAP 643-358-9192.

TUTUILA ISLAND

PAGO PAGO INTL (PPG)(NSTU) 3 SW UTC-11 S14°19.90' W170°42.69' HAWAIIAN-MARIANA

31.2 B Class I, ARFF Index C NOTAM FILE PPG

RWY 05-23: H10001X150 (ASPH-GRVD) S-75, D-170, 2D-250, 2D/2D2-600 PCN 60 F/A/W/T HIRL

RWY 05: MALSR. PAPI(P4L)—GA 3.25° TCH 57'. Thld dsplcd 1002'. Hill. Rgt tfc. 0.4% down.

RWY 23: PAPI(P4L)—GA 3.0° TCH 75'. Thld dsplcd 790'. Fence.

RWY 08-26: H3801X100 (ASPH-GRVD) S-75, D-150, 2D-230, 2D/2D2-550 PCN 45 F/A/W/T HIRL

RWY 08: Rgt tfc.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 05: TORA-9200 TODA-10000 ASDA-9200 LDA-8200

RWY 23: TORA-10000 TODA-10000 ASDA-10000 LDA-9200

SERVICE: S8 FUEL 100, JET A1+ LGT Dusk-Dawn. ACTIVATE MALSR Rwy 05; PAPI Rwy 05 and Rwy 23; HIRL Rwy 05-23 and Rwy 08-26; twy lgts freq—118.3.

AIRPORT REMARKS: Attended continuously. Oloote Mt. 1617' MSL 3.5 miles west of thld Rwy 08. 399' MSL obstruction light on LOG NDB located on hill 2.0 SM southwest of thld Rwy 05. Permanently lighted and marked 226' tower atop Mt. Alava 4.3 SM north-northeast of airport. All flights (except scheduled) prior permission from airport manager required with 24 hour prior notice. All aircraft transitioning Pago Pago (except commercial carriers) must make fuel arrangements with PPG at (684) 733-3158. Sea spray from surf and blow holes may drift across Rwy 05-23 under rough sea conditions. Minor power plant repairs only. Customs available. Landing fee.

CONTINUED ON NEXT PAGE

AIRPORT/FACILITY DIRECTORY

CONTINUED FROM PRECEDING PAGE

AIRPORT MANAGER: 684-733-3154

COMMUNICATIONS: CTAF 122.9

FALEOLO APP/DEP CON 118.1

RADIO AIDS TO NAVIGATION: NOTAM FILE HNL.

(H) VORTACW 112.5 TUT Chan 72 S14°19.96' W170°42.50' at fld. 7.1/12E.

VOR unusable:

005°-032° byd 26 NM blo 16,000'

050°-228° byd 24 NM blo 4,000'

228°-287° byd 34 NM blo 16,000'

287°-005° byd 18 NM

345°-005°

TACAN AZIMUTH unusable:

005°-032° byd 32 NM blo 16,000'

032°-050° byd 34 NM blo 16,000'

287°-005° byd 13 NM

345°-005° byd 5 NM blo 6400'

DME unusable:

005°-032° byd 20 NM blo 16,000'

345°-005° byd 5 NM blo 6400'

NDB (HHW) 403 TUT S14°19.93 W170°43.17 at fld. 12E. Unmonitored.

ILS/DME 110.3 I-TUT Chan 40 Rwy 05 GS unusbl byd 8 NM all alts.

COMM/NAV/WEATHER REMARKS: For IFR clearances ctc Faleolo Air Traffic Control unit phone (685)-42050 or Primary Apch freq 118.1, Secondary Apch freq 118.5, HF freq 6.553. Faleolo tower phone (685)-42530. Christchurch NZ NOF is issuing agency for PAGO PAGO Intl NOTAMS ctc NR 64 33581688. For NOTAM ctc New Zealand (643) 358-1688. FSS: NEW ZEALAND.
