

TISHOMINGO AIRPARK (ØF9) 2 S UTC-6(-5DT) N34°11.91' W96°40.47'

DALLAS-FT WORTH

647 B NOTAM FILE MLC

L-17C

RWY 17-35: H3100X60 (ASPH) S-12 RWY LGTS(NSTD)

RWY 17: Trees.

RWY 35: Trees.

SERVICE: LGT Nstd solar LIRL Rwy 17-35 SS-SR. Rwy 17-35 nstd due to thld lgts all red and edge lgts all yellow. Rotating bcn OTS indef.

AIRPORT REMARKS: Unattended.

AIRPORT MANAGER: (580) 371-8605

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE ADM.

ARDMORE (VH) (H) VORTACW 116.7 ADM Chan 114 N34°12.70' W97°10.09' 086° 24.6 NM to fld. 937/6E.

VOR unusable:

150°-160° byd 40 NM

150°-160° byd 6 NM blo 14,000'

297°-306° byd 40 NM blo 15,000'

307°-314° blo 3,500'

307°-314° byd 15 NM

314°-333°


TACAN AZIMUTH unusable:

314°-333°

DME unusable:

314°-333°

334°-011° byd 39 NM blo 3,100'



TULSA

HARVEY YOUNG (1H6) 8 E UTC-6(-5DT) N36°08.34' W95°49.50'

KANSAS CITY

750 B NOTAM FILE MLC

RWY 17-35: H2580X40 (ASPH)

RWY 17: Trees.

RWY 35: Trees.

RWY N-S: 2580X80 (TURF)

RWY N: Trees.

RWY S: Trees.

SERVICE: S2 FUEL 100LL

AIRPORT REMARKS: Attended Mon-Fri 1400-2300Z±. Arpt unattended federal holidays. Birds on and in/ov airport. Ultralights on and in/ov arpt. Rwy 17 rgt tfc for helicopters. Twys thin & soft in hot weather. Rwy 17-35 severe cracking and raveling. Rwy 17 markings severely faded. Rwy 35 markings svrly faded; nos unrdbl. Rwy N/S rough and uneven.

AIRPORT MANAGER: 918-298-4044

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Tulsa Apch at 918-831-6714/6720.