

JONESVILLE

SWAN CREEK (78A) 3 SW UTC-5(-4DT) N36°12.17' W80°52.06' CINCINNATI

1137 NOTAM FILE RDU

RWY 10-28: 2600X125 (TURF) 1.8% up E

RWY 10: Trees.

RWY 28: Road. Rgt tfc.

RWY 02-20: 921X125 (TURF) 0.4% up S

RWY 02: Road.

RWY 20: Trees.

AIRPORT REMARKS: Unattended. Parachute Jumping. Farm eqpt on and invof arpt. No line of sight btn rwy ends. Rwy 10 slopes uphill, Rwy 02 first half slopes uphill. Rwy 02-20 +60' trees along both sides and not regularly maintained due to wet areas. Twr invof Rwy 28 left base. 4' fence along left edge Rwy 10.

AIRPORT MANAGER: 704-495-9784

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Atlanta ARTCC at 770-210-7692.

JULIAN

KECKS (N88) 2 NE UTC-5(-4DT) N35°55.59' W79°37.65' CHARLOTTE

724 NOTAM FILE RDU

RWY 05-23: 1400X75 (TURF)

RWY 05: Trees.

RWY 23: P-line.

AIRPORT REMARKS: Unattended. AG eqpt ocnl on rwy. Rwy 05 has 4 ft drop off 10 ft fm end of rwy both sides of cntrln. Bldgs on NW edge of rwy. 4' livestock fence below rwy grade across end of each rwy. Arpt in tfc pat of Causey Arpt (2A5) 1 mile NW, CTAF-122.8.

AIRPORT MANAGER: 336-451-1540

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Greensboro Apch at 336-333-5119.

JURLY N35°28.50' W78°25.52' NOTAM FILE JNX. CHARLOTTE

NDB (MHW/LOM) 263 JN 032° 4.3 NM to Johnston Rgnl. 194/9W. NDB unmonitored 2200-1300Z†. L-35B, 36F

NDB unusable:

Byd 15 NM

KATFI N35°01.30' W77°04.77' NOTAM FILE EWN. CHARLOTTE

NDB (LOMW) 362 EW 038° 3.6 NM to Coastal Carolina Rgnl. 38/BW.

KEANS N35°31.97' W82°35.25' NOTAM FILE AVL. ATLANTA

NDB (LOMW) 357 IM 166° 6.2 NM to Asheville Rgnl. 2125/7W.

KECKS (See JULIAN on page 319)