COLORADO

GLENWOOD SPRINGS
KGWS SUMERS AIRPARK (GWS)(KGWS) 3 S UTC-7(-6DT) N39°30.36' W107°18.55' DENVER
5916 NOTAM FILE DEN L-9E
RWY 14–32: H3305X50 (ASPH) S–15 0.3% up NW
RWY14: Trees.
RWY 32: PAPI(P2L)—GA 4.0° TCH 30′. Road.
SERVICE: S4 FUEL 100LL, JET A OX 3, 4
NOISE: Noise abatement: When wind and weather permit use Rwy 32 for arrival and Rwy 14 for departure. No touch and go ldgs.
AIRPORT REMARKS: Attended Mon-Fri 1500-0000Z [‡] . Fuel avbl 24 hrs via self-serve credit card pump. Arpt Manager on call
at 970–445–0965. FBO PH:970–945–3073. Gusty winds frequently in vicinity of arpt. Wildlife on and invof arpt.
Numerous +25' buildings; trees; equipment; tie downs approximately 150' from centerline-both sides of rwy full length.
Rwy 32 has 20' hangars and +30' antenna 200' left of centerline at thld. Paragliding ops vicinity 1 to 2 miles northwest
of arpt up to 18,000 'MSL. Automated super UNICOM. Click 3 times for arpt information.
AIRPORT MANAGER: 970-987-5916
COMMUNICATIONS: CTAF/AUNICOM 123.0
GLENWOOD SPRINGS RCO 122.2 (DENVER RADIO)
CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Denver ARTCC at 303-651-4257.
RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.
RED TABLE (VH) (DH) VORW/DME 113.0 DBL Chan 77 N39°26.36′W106°53.68′ 270° 19.7 NM to fld. 11800/12E.
VOR unusable:
040°-056° byd 40 NM
057°-074° byd 40 NM blo 16,300´ 057°-074° byd 65 NM
075°-100° byd 40 NM
115°-130° byd 40 NM
160°-200° byd 40 NM
COMM/NAV/WEATHER REMARKS: Automated UNICOM, 3 clicks adzy.