

WALDEN—JACKSON CO (33V) 1 NE UTC-7(-6DT) N40°45.02' W106°16.29'

8154 B NOTAM FILE DEN

CHEYENNE

H-3F, 5A, L-9E, 11E

IAP

Rwy 04-22: H5900X75 (ASPH) S-25 MIRL

Rwy 04: PAPI(P4L)—GA 3.0° TCH 35'.

Rwy 22: PAPI(P4L)—GA 3.0° TCH 35'.

Rwy 17-35: 4020X100 (TURF) 0.4% up S

Rwy 17: Fence.

Rwy 35: Road.

SERVICE: LGT ACTVT PAPI Rwy 04 and 22; MIRL Rwy 04-22—CTAF.

AIRPORT REMARKS: Attended on call—amgr or 970-723-4481 or 970-846-6971. Rdo ctl model acft ops SE corner of arpt; deer and antelope on rws. Rwy 04-22 asph pvmt usbl but cracked thrut and delaminating at apch ends. Rwy 04 has +20 ft pline 660 ft fm rwy end 750 ft L of cntrln; 50 ft dropoff 450 ft fm thr. Rwy 04 worn and eroded. Rwy 22 worn and eroded; thr mkd 125 ft fm end. Rwy 17 marked with orange cones. Rwy 35 marked with orange cones. Rwy 17 6 ft pole 100 ft fm thr 10 ft L of rwy edge. Rwy 35 +38 ft trees 300 ft fm thr 154 ft R of apch end; +4 ft fence at thr L & R; fence posts mkd with worn & faded yellow paint; road 24 ft fm thr.

AIRPORT MANAGER: 970-723-4660

WEATHER DATA SOURCES: AWOS-3 118.625 (970) 723-4513.

COMMUNICATIONS: CTAF 122.9

® **DENVER CENTER APP/DEP CON** 126.5

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE DEN.

KREMMLING (VH) (DH) VOR/DME 113.8 RLG Chan 85 N40°00.16' W106°26.55' 356° 45.5 NM to fld.
9415/14E.

DME unusable:

285°-305° byd 34 NM blo 16,300'

VOR unusable:

040°-050° byd 40 NM blo 16,000'

040°-050° byd 55 NM

051°-061° byd 40 NM

062°-072° byd 40 NM blo 15,600'

062°-072° byd 64 NM

073°-085° byd 40 NM blo 15,000'

073°-085° byd 48 NM

086°-119° byd 40 NM

120°-130° byd 40 NM blo 16,500'

120°-130° byd 62 NM

131°-185° byd 40 NM

187°-197° byd 40 NM

217°-221° byd 40 NM

260°-320° byd 40 NM

350°-039° byd 40 NM