
NEW RICHMOND RGNL (RNH)(KRNH) 2 N UTC-6(-5DT) N45°08.87' W92°32.35'**GREEN BAY**

998 B NOTAM FILE RNH

H-21, L-141, A

RWY 14-32: H5507X75 (ASPH) S-30, D-60 MIRL

IAP

RWY 14: REIL. PAPI(P4L)—GA 3.0° TCH 40'. Tree.**RWY 32:** REIL. PAPI(P4L)—GA 3.0° TCH 20'.**RWY 04-22:** 2006X75 (TURF)**SERVICE:** S4 **FUEL** 100LL, JET A **OX** 4 **LGT** MIRL Rwy 14-32 preset on low inst; to incr instst and ACTVT REIL Rwy 14 and Rwy 32; PAPI Rwy 14 and Rwy 32; MIRL Rwy 14-32—CTAF. PAPI Rwy 32 unusbl byd 4 deg R of course.**AIRPORT REMARKS:** Attended continuously. 24 hr self fuel avbl for credit card users or call 715-246-5338. Seaplane tfc adjacent to south side of arpt. Deer and birds on and invof arpt. Aerobatic practice area 4NM northeast of arpt. Ultralight activity on and invof arpt. Turbo-jet touch and go not authorized. Bright lgts from ball fields 1/2 mile south during evenings May thru Sep. Rwy 04-22 marked with white cones. Open to ski equipped acft winter months. Automobile and pedestrian access onto arpt property restricted by security fencing and gates from 0400-1200Z†. Contact arpt manager 715-246-7735 for access instructions.**AIRPORT MANAGER:** 715-246-7735**WEATHER DATA SOURCES:** AWOS-3 120.0 (715) 246-3202.**COMMUNICATIONS:** CTAF/UNICOM 122.975® **MINNEAPOLIS APP/DEP CON** 121.2**GCO** 121.725 (MINNEAPOLIS APCH CTL)**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis Apch at 612-726-9086.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PNM.**GOPHER (VH) (H) VORTACW** 117.3 GEP Chan 120 N45°08.74' W93°22.39' 083° 35.4 NM to fld. 877/6E.

VOR unusable:

061°-071° byd 40 NM

067°-080° byd 47 NM blo 3,000'

067°-080° byd 70 NM blo 12,000'

239°-277° byd 40 NM blo 18,000'

• • • • • • • • • • • • • • • •
HELIPAD H1: H40X40 (ASPH)

NORTH COUNTRY SPB (See SOLON SPRINGS on page 389)

OCONTO/J DOUGLAS BAKE MUNI (OCQ)(KOCQ) 2 SW UTC-6(-5DT) N44°52.44' W87°54.59'**GREEN BAY**

604 B NOTAM FILE GRB

L-31A

RWY 11-29: H3199X75 (ASPH) S-40, D-55, 2D-90 MIRL

IAP

RWY 11: REIL. PAPI(P2L)—GA 4.0° TCH 31'. Trees.**RWY 29:** REIL. PAPI(P2L)—GA 4.0° TCH 31'.**RWY 04-22:** 1840X150 (TURF)**SERVICE:** **FUEL** 100LL **LGT** MIRL Rwy 11-29 preset to low SS-SR; to incr instst and actvt REIL Rwy 11 and 29; MIRL Rwy 11-29—CTAF. PAPI Rwy 11 and 29 ops consly. Rwy 29 PAPI unusbl byd 8 degs right of cntrln.**AIRPORT REMARKS:** Attended Mon-Fri irregularly. Migratory waterfowl on & invof arpt. 100LL: 24 hr self svc fuel avbl with credit card. Confirm winter rwy conditions and snow removal with amgr 920-834-7727. Rwy 04-22 not plowed Nov-Apr. Rwy 04 and 22 mkd with white cones.**AIRPORT MANAGER:** 920-834-7727**WEATHER DATA SOURCES:** AWOS-3 120.925 (920) 835-1599.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **GREEN BAY APP/DEP CON** 120.3 (1130-0530Z† other times ctc)® **MINNEAPOLIS APP/DEP CON** 124.4**CLEARANCE DELIVERY PHONE:** For CD ctc Green Bay Apch at 920-431-5741, when Green Bay Apch clsd, for CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE GRB.**GREEN BAY (VH) (H) VORTACW** 115.5 GRB Chan 102 N44°33.31' W88°11.69' 031° 22.7 NM to fld. 767/1E.

VOR unusable:

000°-025° byd 40 NM

026°-036° byd 40 NM blo 2,600'

026°-036° byd 49 NM

040°-065° byd 59 NM

221°-233° byd 40 NM

255°-265° byd 40 NM

270°-300° blo 7,000'