

**WESTWINDS** (D17) 4 W UTC-7(-6DT) N38°45.51' W108°08.91'

**DENVER**  
L-9E

5000 NOTAM FILE DEN

**RWY 04-22:** H4100X40 (ASPH)

**RWY 22:** Trees.

**RWY 13-31:** 2000X70 (GRVL-DIRT)

**RWY 13:** Hill.

**RWY 31:** Road.

**AIRPORT REMARKS:** Attended 1500-0000Z. Rwy 04-22 CLOSED to acft 8,500 lbs or more. Wildlife on and invof arpt. +100' to 300' mountains lctd north, west and east of arpt at varying distances. Rwy 22 has 180' mountain 1500' from rwy end, apch slope 7:1. Rwy 13-31 soft when wet. Rwy 31 has +10' trees 150' from thld OB. +40' tree 60' from thld 50' rgt of cntrln. Rwy 04 has +120' terrain 2700' from thld 380' left of cntrln.

**AIRPORT MANAGER:** 303-829-1696

**COMMUNICATIONS:** CTAF/UNICOM 122.8

**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE MTJ.

**MONTROSE (VH) (H) VOR/DME** 117.1 MTJ Chan 118 N38°30.39' W107°53.96' 310° 19.1 NM to fld.  
5713/12E. vDME unmonitored.

DME unusable:

011°-090° byd 26 NM blo 15,000'

190°-250° byd 25 NM blo 15,000'

VOR unusable:

001°-167° byd 40 NM

060°-090° byd 26 NM blo 16,000'

167°-178° byd 50 NM

168°-178° byd 40 NM blo 16,300'

179°-251° byd 40 NM

190°-250° byd 25 NM blo 15,000'

252°-262° byd 40 NM blo 13,000'

252°-262° byd 51 NM blo 15,500'

252°-262° byd 72 NM

263°-295° byd 40 NM

313°-360° byd 40 NM

## DENVER

**CENTENNIAL** (APA)(KAPA) 15 SE UTC-7(-6DT) N39°34.21' W104°50.96'

**DENVER**  
H-3F, 5A, L-10F, A  
IAP, AD

5885 B NOTAM FILE APA

**RWY 17L-35R:** H10001X100 (ASPH-GRVD) S-56, D-75, 2S-95 PCN 26 F/C/X/T MIRL

**RWY 17L:** PAPI(P4L)—GA 3.0° TCH 47'. 1.0% up.

**RWY 35R:** MALSR. PAPI(P4L)—GA 3.0° TCH 49'. P-line. Rgt tfc. 0.8% down.

**RWY 17R-35L:** H7001X75 (ASPH-GRVD) S-30 PCR 339 F/C/X/T MIRL 0.9% up S

**RWY 17R:** REIL. PAPI(P4L)—GA 3.0° TCH 42'. Rgt tfc.

**RWY 35L:** REIL. PAPI(P4R)—GA 3.0° TCH 37'. Fence.

**RWY 10-28:** H4800X75 (ASPH-GRVD) S-12.5 PCN 17 F/A/Y/T MIRL 0.6% up W

**RWY 10:** PAPI(P2L)—GA 3.0° TCH 44'. Thld dsplcd 400'.

**RWY 28:** REIL. PAPI(P2L)—GA 3.0° TCH 41'. Pole.

**SERVICE:** S4 FUEL 100LL, JET A, UL94 OX1, 2

**NOISE:** Noise abatement proc in efct. All acft avoid noise sensitive areas 1 NM north and west of arpt and 1 NM southeast of arpt. Rwy 17R-35L clsd tfc remain south of Arapahoe Road, east of I-25, and north of Lincoln Ave. Quiet hrs 0500-1400Z. Tbjt acft use NBAA profiles. Noise office—303-790-0598. See Special Notices—Centennial Airport Voluntary Noise Abatement Guidelines.

**AIRPORT REMARKS:** Attended continuously. 100LL: Self serve fuel avbl. Waterfowl on and in vicinity of arpt. Mult lrg pwr lines apply 3 NM S of Rwy 35R and Rwy 35L. Numerous cranes invof arpt. Nmrs flood lgts 1/2 SM N of thr; SS-0700Z. Adzy density alt dspl lctd C-1, A-1, and A-18. +109' twr located 1800' east/northeast of Rwy 17L thld. All acft blo cert 70,000 lb max gross tkof wt and Stage III acft up to cert 75,000 lb max gross tkof wt may opr; one-time exception auzd by Exec Dir. Heli ops ctc FBO for lndg zone lctn; heli ops on front ramp not advised. User fee arpt: H24 U.S. Customs—303-768-0309. CTN: Ensure proper rwy alnmt; close spaced parl rwys. Arpt safety video—[https://www.faa.gov/airports/runway\\_safety/videos/apa/](https://www.faa.gov/airports/runway_safety/videos/apa/). NOTE: See Special Notices—USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado. See Special Notices—Arrival Alert.

**AIRPORT MANAGER:** 303-790-0598

**WEATHER DATA SOURCES:** ASOS (720) 873-2799 TDWR.

**COMMUNICATIONS:** ATIS 120.3 303-799-6722 UNICOM 122.95

DENVER RCO 122.2 (DENVER RADIO)

DENVER APP/DEP CON 132.75

TOWER 118.9 GND CON 121.8 CLNC DEL 128.6

**AIRSPACE:** CLASS D svc continuous.

CONTINUED ON NEXT PAGE

