

**ANN ARBOR MUNI** (ARB)(KARB) 3 S UTC-5(-4DT) N42°13.38' W83°44.74'

839 B NOTAM FILE ARB

**RWY 06-24:** H3505X75 (CONC-GRVD) S-45, D-70 MIRL

**RWY 06:** REIL. PAPI(P4L)—GA 3.0° TCH 20'.

**RWY 24:** VASI(V2L)—GA 3.0° TCH 20'. Tree.

**RWY 12-30:** 2750X110 (TURF) 0.6% up NW

**RWY 30:** Tree.

**SERVICE:** S4 FUEL 100LL, JET A+ OX1, 2, 3, 4 LGT When ATCT clsd ACTVT REIL Rwy 06, PAPI Rwy 06, VASI Rwy 24, MIRL Rwy 06-24—CTAF.

**AIRPORT REMARKS:** Attended Apr-Oct 1300-0100Z†, Nov-Mar 1300-2300Z†. Trml open 1200Z†-dusk. Deer and lrg birds on and invof arpt. When ATCT clsd confirm snow removal ops and winter conditions—CTAF. No snow removal for Rwy 12-30. Rwy 24 runup area, first 200' of Twy A, Twy A1 between Twy A and Rwy 24 hold line not vsb fm twr. Rwy 12-30 marked with 3' yellow cones.

**AIRPORT MANAGER:** 734-794-6312

**WEATHER DATA SOURCES:** ASOS (734) 668-7173 LAWRS.

**COMMUNICATIONS:** CTAF 120.3 ATIS 134.55 UNICOM 123.0

Ⓡ **DETROIT APP/DEP CON** 118.95

**TOWER** 120.3 (1300-0100Z†) **GND CON** 121.6 **CLNC**

**DEL** 121.6

**CLEARANCE DELIVERY PHONE:** For CD when ATCT is clsd ctc Detroit Apch at 734-955-1404.

**AIRSPACE:** CLASS D svc 1300-0100Z†; other times CLASS G.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE LAN.

**SALEM (L) VORTACW** 114.3 SVM Chan 90 N42°24.52' W83°35.63' 214° 13.0 NM to fld. 956/3W.

**TACAN AZIMUTH** unusable:

215°-255° byd 10 NM

**VOR** unusable:


094°-121° byd 10 NM blo 5,000'

094°-121° byd 20 NM blo 8,000'

**DME** unusable:

099°-115° byd 15 NM blo 5,000'

099°-115° byd 20 NM blo 8,000'



**DETROIT**  
**COPTER**  
**L-28J, A**  
**IAP, AD**

**ANTRIM CO** (See BELLAIRE on page 157)

**ARNOLD FLD** (See CROSWELL on page 169)