300 OHIO

## **NEWTON FALLS**

**BRACEVILLE** (41N) 2 N UTC-5(-4DT) N41°12.67′ W80°58.16′

DETROIT L-30G

900 NOTAM FILE CLE **RWY 01–19**: H3000X30 (ASPH)

RWY 01: Thid dsplcd 55'. Brush.

RWY 19: Trees.

AIRPORT REMARKS: Attended irregularly. Deer, birds, and wildlife on and invof arpt. Rwy 01–19 extsv cracking. Rwy 01–19 markings faded. Rwy 01–19 NSTD basic due to size and spacing.

AIRPORT MANAGER: 440-552-1082

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Youngstown Apch at 330-856-4806, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.

RADIO AIDS TO NAVIGATION: NOTAM FILE CAK.

**AKRON (L) (L) VORW/DME** 114.4 ACO Chan 91 N41°06.47′ W81°12.09′ 063° 12.2 NM to fld. 1197/4W. DME unusable: Byd 10 NM

NOBLE CO (See CALDWELL on page 260)

NORTH BASS ISLAND (3X5) 0 NW UTC-5(-4DT) N41°43.08′ W82°49.27′

DETROIT

594 NOTAM FILE CLE

RWY 01-19: H1804X60 (ASPH) 0.3% up S

RWY 01: Trees. RWY 19: Rgt tfc.

AIRPORT REMARKS: Unattended. No touch and go landings and no student training. No ops dusk-dawn. Arpt lctd NW corner of island.

AIRPORT MANAGER: 419-285-3371 COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Detroit Apch at 734-955-1404.

NORTHEAST OHIO RGNL (See ASHTABULA on page 255)