

PORT CLINTON**ERIE-OTTAWA INTL** (PCW)(KPCW) 3 E UTC-5(-4DT) N41°30.98' W82°52.17'**DETROIT**
H-10G, L-30F
IAP

590 B LRA NOTAM FILE PCW

RWY 09-27: H5646X100 (ASPH-GRVD) S-100 HIRL**RWY 09:** REIL. PAPI(P4L)—GA 3.0° TCH 40'. Tree.**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 40'. Thld dspcd 201'. Trees.**RWY 18-36:** H4002X75 (ASPH) MIRL**RWY 36:** Trees.**SERVICE:** S4 **FUEL** 100LL, JET A+ **OX** 1, 2, 3, 4 **LGT** Actvt REIL Rwy 09 & 27; HIRL Rwy 09-27; MIRL Rwy 18-36—CTAF. PAPI Rwy 09 & 27 opr consly.**AIRPORT REMARKS:** Attended 1200-2300Z±. Occnl deer, birds and otr wildlife on & invof arpt. Rwy 27 calm wind rwy. Taxilane A clsd to acft with wingspan more than 49 ft. Cust avbl 24 hrs 7 days per week. Req must be made two prior to arr. Lcl ofc 419-732-4446. Hngr transient storage: PPR.**AIRPORT MANAGER:** 419-734-6297**WEATHER DATA SOURCES:** AWOS-3 118.775 (419) 734-9955.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **CLEVELAND APP/DEP CON** 126.35**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland Apch at 216-352-2323.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CLE.**DRYER (VH) (DH) VOR/DME** 113.6 **DJB** Chan 83 N41°21.48' W82°09.72' 292° 33.3 NM to fld. 780/5W.

VOR unusable:

001°-010° byd 40 NM

020°-024° byd 40 NM

080°-095° byd 40 NM

110°-120° byd 40 NM

135°-145° byd 40 NM

135°-150°

155°-165°

160°-165° byd 40 NM

185°-195° byd 40 NM

187°-197°

210°-224° byd 40 NM

211°-218°

225°-235° byd 40 NM blo 11,000'

225°-235° byd 95 NM

225°-245° byd 20 NM blo 3,500'

245°-265° byd 40 NM

275°-285° byd 40 NM blo 18,000'

286°-355° byd 40 NM

DME unusable:

187°-197°

289°-310°

322°-332°

350°-060°

PORTAGE CO (See RAVENNA on page 306)