

MARSHFIELD MUNI – GEORGE HARLOW FLD (GHG)(KGHG) 2 E UTC-5(-4DT) N42°05.85'**NEW YORK**

W70°40.38'

COPTER

9 B NOTAM FILE BDR

L-33D**RWY 06-24:** H3900X100 (ASPH-GRVD) S-12.5, D-38.8**IAP**

PCN 190F/B/X/T MIRL

RWY 06: REIL. PAPI(P4R)—GA 3.0° TCH 43'. Thld dspcd 300'. Trees.**RWY 24:** REIL. PAPI(P4R)—GA 3.0° TCH 40'. Thld dspcd 300'. Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 06:** TORA-3900 TODA-3900 ASDA-3600 LDA-3300**RWY 24:** TORA-3900 TODA-3900 ASDA-3600 LDA-3300**SERVICE:** S4 FUEL 100LL, JET A, A+ OX 1, 3 LGT ACTVT PAPI Rwy 06 and 24—CTAF.**NOISE:** Voluntary noise abatement procs in effect, no touch and go lds between 2100-0730 local. All engine runups at midfield ramp.**AIRPORT REMARKS:** Attended 1300-0000Z†. Birds, deer and wildlife on and in/ov arpt. Flt training activity. After hrs service by request. Sfc conds unmnt and snow removal not available 0030-1400Z†.**AIRPORT MANAGER:** 781-834-4928**WEATHER DATA SOURCES:** AWOS-3 120.0 (781) 837-0555. LAWRS.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **BOSTON APP/DEP CON** 124.1**CLEARANCE DELIVERY PHONE:** For CD ctc Boston Apch at 603-594-5554.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BOS.**BOSTON (VH) (DH) VOR/DME** 112.7 BOS Chan 74 N42°21.45' W70°59.37' 154° 21.0 NM to fld. 18/16W.

VOR unusable:

043°-053° byd 40 NM blo 5,000'

043°-053° byd 74 NM

055°-065° byd 40 NM blo 5,000'

055°-065° byd 47 NM

061°-104° byd 18 NM blo 2,000'

070°-108° byd 40 NM

109°-119° byd 40 NM blo 6,000'

109°-119° byd 58 NM

120°-148° byd 40 NM

149°-167° byd 40 NM blo 2,100'

149°-167° byd 83 NM

168°-177° byd 40 NM

178°-188° byd 40 NM blo 11,000'

178°-188° byd 50 NM

204°-262° byd 40 NM

263°-273° byd 40 NM blo 4,000'

263°-273° byd 54 NM

271°-060° byd 25 NM blo 3,500'

274°-337° byd 40 NM

350°-042° byd 40 NM

DME unusable:

061°-104° byd 18 NM blo 2,000'

271°-060° byd 25 NM blo 3,500'

