

GREENE (4N7) 2 SW UTC-5(-4DT) N42°18.25' W75°47.23'

NEW YORK

935 NOTAM FILE BUF

RWY 07-25: 2665X200 (TURF) RWY LGTS(NSTD)

RWY 07: Pole.

RWY 25: Tree.

SERVICE: LGT ACTIVATE LIRL Rwy 07-25 4 clicks—CTAF. Rwy 07-25 NSTD low intensity lgts; non-std edge and end lgts.

AIRPORT REMARKS: Attended daltg hrs. Rwy 25 has numerous +30' -90' trees, both sides at thld. Rwy numbers etched into turf sfc both ends. Deer and geese on and infov arpt. During winter check FSS for NOTAMs.

AIRPORT MANAGER: (607) 358-5801

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc New York ARTCC at 631-468-1425.

GREENVILLE-RAINBOW (1H4) 1 E UTC-5(-4DT) N42°25.18' W74°00.41'

NEW YORK

840 NOTAM FILE BTW

RWY 01-19: 1801X75 (TURF)

RWY 01: Trees.

RWY 19: Thld dspld 112'. Trees.

AIRPORT REMARKS: Attended May-Nov. daltg hrs. Arpt CLOSED Dec 1-Apr 1. Rwy 01-19 may be clsd after rains due to wetness. Rwy 01-19 soft and wet during Mar-Jun. +30' p-line parallel to and 150' west of rwy centerline. Rwy 19 edges and thld marked by white markers (1' square). Rwy 01 edges and dspld thld marked by white markers (1' square), end of usable rwy not marked and is 112' north of white thld markers.

AIRPORT MANAGER: 518-966-5343

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Albany Apch at 518-862-2299.

GRIFFISS INTL (See ROME on page 240)

HAMBURG (4G2) 4 W UTC-5(-4DT) N42°42.05' W78°54.89'

DETROIT

751 NOTAM FILE BUF

RWY 01-19: H2465X30 (ASPH) LIRL(NSTD)

RWY 01: Thld dspld 462'. Trees.

RWY 19: Thld dspld 456'. Tree.

SERVICE: FUEL 100LL LGT ACTIVATE LIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Unattended. Deer on and infov arpt. Ultraigt act on and infov arpt. Rwy 01: 100' drop off, 150' south of rwy end. Rwy 01-19 nstd LIRL due to spacing and colors. Dthr not lgtd. Rwy 01-19 no cntrln.

AIRPORT MANAGER: 716-472-6318

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0490.

HAMILTON MUNI (VGC)(KVGC) 1 NW UTC-5(-4DT) N42°50.61' W75°33.67'

NEW YORK

1137 NOTAM FILE BUF

H-101, 11C, 12J, L-32F

RWY 17-35: H5314X75 (ASPH-GRVD) S-20, D-60 MIRL

IAP

RWY 17: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Thld dspld 300'. Trees.

RWY 35: REIL. PAPI(P2L)—GA 4.0° TCH 40'. Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 17: TORA-5314 TODA-5314 ASDA-5314 LDA-5014

RWY 35: TORA-5314 TODA-5314 ASDA-5014 LDA-5014

SERVICE: S4 FUEL 100LL, JET A, A+ LGT Actvt MIRL Rwy 17-35;

REIL Rwy 17 and 35-122.7.

NOISE: Noise abatement procedures in effect; all acft departures maintain rwy heading until 2100' MSL before making turn out.

AIRPORT REMARKS: Attended 1400-2200Z. Migratory birds on and infov arpt spring and fall. Deer on and infov Rwy 17-35. Ultraigts on and infov arpt. Glidr ops infov of arpt. After hrs fuel avbl by appointment for a fee ctc arpt mgr. Maintenance shop airframe/powerplant and inspection authorization avbl Mon-Fri 1400-2200Z. Rwy 17-35 south end has 572' safety area. Rwy 17: Windmills 3 miles N of arpt. Taxi svc and car rental avbl.

AIRPORT MANAGER: 315-824-1111

WEATHER DATA SOURCES: AWOS-3P 119.425 (315) 824-1825.

COMMUNICATIONS: CTAF/UNICOM 123.0

® SYRACUSE APP/DEP CON 126.125

CLEARANCE DELIVERY PHONE: For CD ctc Syracuse Apch at 315-455-6218.

RADIO AIDS TO NAVIGATION: NOTAM FILE BUF.

GEORGETOWN (L) TACAN Chan 125 GGT (117.8) N42°47.34' W75°49.60' 085° 12.2 NM to fld. 2040/11W.

