## BENSALEM

**TOTAL RF HELIPORT** (ØØA) 1 E UTC-5(-4DT) N40°04.25′ W74°56.02′

**NEW YORK** 

9 NOTAM FILE IPT

HELIPAD H1: H80X80 (ASPH) PERIMETER LGTS

HELIPORT REMARKS: Unattended, After hrs 215-990-5300, Ingress/egress 290°-110° and 20′-200′.

AIRPORT MANAGER: 215-990-5300 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Philadelphia Apch at 800-354-9884.

## BERMUDIAN VALLEY AIRPARK (See KRALLTOWN on page 283)

## **BETHEL**

GRIMES (8N1) 2 E UTC-5(-4DT) N40°29.09′ W76°15.81′

NFW YORK

582 NOTAM FILE IPT RWY 11-29: 2720X100 (TURF) RWY 11: Thid dsplcd 250'. Road.

RWY 29: Thid dsplcd 270'. Tree.

AIRPORT REMARKS: Attended irregularly. AD CLSD SS-SR. Parachute Jumping. Rwy 11-29 first 700 ft of rwy on W end unusbl dur early spring due to wet conds. Rwy 11 and Rwy 29 mkd with white discs. Rwy 11-29 dthr mkd by red discs.

AIRPORT MANAGER: 717-933-9566 COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Harrisburg Apch at 800-932-0712.

BLOOMSBURG MUNI (N13) 0 E UTC-5(-4DT) N40°59.86′ W76°26.11′ 481 B NOTAM FILE IPT

NEW YORK L-30J

IAP

RWY 09-27: H3200X60 (ASPH) S-12.5 MIRL

RWY 09: Road


SERVICE: S4 FUEL 100LL LGT ACTIVATE MIRL Rwy 09-27-CTAF. AIRPORT REMARKS: Attended irregularly. Call and for assistance. For svc after hrs call 570-317-1966. Deer and geese invof rwy. After dusk, Rwy 09 preferred due to deer act east end of arpt.

AIRPORT MANAGER: 570-317-1966 COMMUNICATIONS: CTAF/UNICOM 122.8 ®WILKES-BARRE APP/DEP CON 120.95

CLEARANCE DELIVERY PHONE: For CD ctc Wilkes-Barre Apch at 570-655-2084.

RADIO AIDS TO NAVIGATION: NOTAM FILE IPT.

MILTON (L) (L) VORTACW 109.2 MIP Chan 29 N41°01.40′ W76°39.92′ 107° 10.6 NM to fld. 1000/9W.



BRADEN AIRPARK (See EASTON on page 271)

BRADFORD CO (See TOWANDA on page 310)