

CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE BTV.

BURLINGTON (VL) VOR/DME 117.5 BTV Chan 122 N44°23.83' W73°10.96' 086° 25.8 NM to fld. 417/15W.

VOR unusable:

030°-086° byd 40 NM
 075°-132° byd 30 NM blo 9,000'
 087°-097° byd 40 NM blo 9,000'
 087°-097° byd 49 NM
 098°-169° byd 40 NM
 133°-165° byd 30 NM blo 8,000'
 170°-180° byd 40 NM blo 5,800'
 170°-180° byd 47 NM
 181°-196° byd 40 NM
 244°-292° byd 40 NM
 340°-350° byd 40 NM blo 6,000'
 351°-010° byd 40 NM

DME unusable:

075°-132° byd 30 NM blo 9,000'
 133°-165° byd 30 NM blo 8,000'

NEWPORT

NORTHEAST KINGDOM INTL (EFK)(KEFK) 3 SW UTC-5(-4DT) N44°53.29' W72°13.72'

MONTREAL

934 B LRA NOTAM FILE BTV

H-11D, L-32H

RWY 18-36: H5301X100 (ASPH) S-30, D-44 PCN 33 F/D/X/T MIRL

IAP

RWY 18: REIL. PAPI(P4L)—GA 3.0° TCH 43'. Thld displd 299'.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 44'. Ground.

RWY 05-23: H3996X100 (ASPH) S-30, D-44

RWY 05: Trees.

RWY 23: Pole.

SERVICE: S4 FUEL 100LL, JET A+ LGT ACTVT PAPI Rwy 18 and 36; MIRL Rwy 18-36—CTAF.

AIRPORT REMARKS: Attended 1400-2200Z. 100LL and Jet A+ fuel 24 hr self svv. Mobile fuel vehicle when atndd. Rwy conds not mnt when unattd. Rwy 05 extsv cracking, shoulders failed. Gulls on and in vicinity of arpt. Cold temperature airport. Altitude correction required at or below -32C.

AIRPORT MANAGER: 802-279-9746

WEATHER DATA SOURCES: AWOS-3P 118.275 (802) 334-4427.

COMMUNICATIONS: CTAF/UNICOM 122.8

NEWPORT RCO 122.5 (BURLINGTON RADIO)

Ⓡ BOSTON CENTER APP/DEP CON 135.7


CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE BML.

BERLIN (H) DME 116.55 BML Chan 112(Y) N44°38.01' W71°11.17' 289° 47.1 NM to fld. 1730.

DME unusable:

080°-125° blo 10,000'
 188°-198° blo 10,000'
 275°-292° blo 10,000'



NORTHEAST KINGDOM INTL (See NEWPORT on page 331)

PATRICK LEAHY BURLINGTON INTL (See BURLINGTON on page 326)

POST MILLS (2B9) 0 E UTC-5(-4DT) N43°53.02' W72°15.13'

NEW YORK

696 NOTAM FILE BTV

RWY 04-22: 2900X80 (TURF)

RWY 04: Trees. Rgt tfc.

RWY 22: Road.

RWY 05-23: 2300X80 (TURF) 0.8% up NE

RWY 05: Trees. Rgt tfc.

RWY 23: Road.

AIRPORT REMARKS: Attended irregularly. Ultralights; gliders and hot air balloons on and invov arpt. Arpt open to ski acft only when snow covered. No snow removal. See snowtam rprts. Propane avbl for hot air balloons. Rwy 04-22: 70 ft trees, 40 ft E of cntrl, S 1700 ft.

AIRPORT MANAGER: 802-333-9254

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.