

PORT OF DEL BONITA**WHETSTONE INTL** (H28) 32 NW UTC-7(-6DT) N49°00.00' W112°47.55'

GREAT FALLS

4336 LRA NOTAM FILE GTF

RWY 07-25: 4440X65 (TURF)**RWY 07:** P-line.**AIRPORT REMARKS:** Unattended. No snow removal. Rwy 07-25 gopher holes. Rwy 07 p-line marked with red balls. Rwy 07-25 thr mkd by double cones; edge mkd by white cones spaced 200'.**AIRPORT MANAGER:** 406-444-2506**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**RAVALLI CO** (See HAMILTON on page 117)**RED LODGE** (RED)(KRED) 1 NW UTC-7(-6DT) N45°11.09' W109°15.46'

GREAT FALLS

5762 B NOTAM FILE GTF

L-13D

RWY 16-34: H4000X75 (ASPH) S-4, D-6 MIRL 1.6% up S**RWY 16:** VASI(V2L)—GA 3.0° TCH 27'. Tree.**RWY 34:** Road.**SERVICE:** FUEL 100LL LGT ACTVT VASI Rwy 16; MIRL Rwy 16-34—CTAF.**NOISE:** Noise abatement proc in efct: Pilots reqstd to: Rwy 16 ARR fly dnwnd at tfc pat alt ovr bluff E of downtown and when safe and practical fly high angle final app slp; Rwy 34 Dep, mnvr on upwind to W of the residential area N of arpt as soon as safe and practical; Rwy 34 ARR,: Fly dnwnd W of residential area W. Crosswind grass strips; limit opns to/from xwind grass strips and fly std tfc patterns at TPA to minimize impacts upon city downtown and residential areas immediately E of arpt.**AIRPORT REMARKS:** Unattended. Wildlife on and infov rwy. Cond unmnt; See <https://weathercams.faa.gov> for current rwy conds-amgr. Fuel H24 credit card; avblty - 715-781-7054. Grass strip ops; fly std tfc pat alt; lmt ops. Rwy 34 rwy end +4' fence and +10' road 100-110' right x cntrln 288' fm thr. -400' trnn dropoff 150' R. Rwy 16-34 edge cracking and eroding; loose sfc grvl. Rwy 16 mrkgs faded; ptns misc. Rwy 34 mrkgs faded.**AIRPORT MANAGER:** 406-425-3143**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BIL.**BILLINGS (VH) (H) VORTACW** 114.5 BIL Chan 92 N45°48.51' W108°37.48' 202° 46.0 NM to fld. 3811/14E.


VOR unusable:

146°-154° byd 40 NM

155°-165° byd 40 NM blo 11,000'

155°-165° byd 49 NM blo 18,000'

166°-173° byd 40 NM

COMM/NAV/WEATHER REMARKS: Automated UNICOM: 2 clicks on 122.725.**RICHEY** (7U8) 1 SW UTC-7(-6DT) N47°37.59' W105°04.78'

BILLINGS

2494 NOTAM FILE GTF

RWY 14-32: 2690X75 (TURF-DIRT)**RWY 32:** Hill.**AIRPORT REMARKS:** Unattended. AER 14 has dip obscured by grass prior to thld. No snow removal.**AIRPORT MANAGER:** 406-444-2506**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**RIDDICK FLD** (See PHILIPSBURG on page 134)**ROCK CREEK** (See CLINTON on page 102)