

MC DERMITT STATE (26U) 0 W UTC-8(-7DT) N42°00.62' W117°43.63'

KLAMATH FALLS
H-30, L-11B

4478 B NOTAM FILE MMV

RWY 16-34: H5900X60 (ASPH) S-12.5 PCN 13 F/C/X/T MIRL

1.0% up N

SERVICE: LGT ACTIVATE MIRL Rwy 16-34—CTAF.

AIRPORT REMARKS: Unattended. Surface conditions not reported. P-lines South and East.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE REQ.

ROME (VH) (DH) VORW/DME 112.5 REO Chan 72 N42°35.43'

W117°52.09' 151° 35.4 NM to fld. 4040/19E.

DME unusable:

095°-105° byd 30 NM blo 10,000'

115°-125° byd 30 NM blo 10,000'

VOR unusable:

011°-021° byd 40 NM

044°-054° byd 40 NM blo 31,000'

055°-119° byd 40 NM

120°-130° byd 40 NM blo 29,000'


131°-179° byd 40 NM

180°-190° byd 40 NM blo 19,000'

191°-214° byd 40 NM

225°-303° byd 40 NM

304°-315° byd 40 NM blo 18,000'



MC KENZIE BRIDGE STATE (ØØS) 3 E UTC-8(-7DT) N44°10.89' W122°05.13'

KLAMATH FALLS

1620 NOTAM FILE MMV

RWY 06-24: 2600X90 (TURF)

RWY 06: Trees.

RWY 24: Trees.

AIRPORT REMARKS: Unattended. Arpt CLOSED Nov 1-May1. Wildlife on and invof arpt year round. Owner advises ctc with Oregon Dept of Aviation 503-378-4880 prior to use. Rwy 06-24 slopes up to the east. Expect significant turbulence and downdrafts near rwy. Rwy 06-24 rough on east half. Land east-tnk west. Rwy 06 thld marked with white mats. Rwy edges marked with white panel markers. Sfc conds not rptd.

AIRPORT MANAGER: 503-378-4880

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.