

SARATOGA

SHIVELY FLD (SAA)(KSAA) 1 SW UTC-7(-6DT) N41°26.61' W106°49.65'

7014 B NOTAM FILE CPR

RWY 05-23: H8801X100 (ASPH-GRVD) S-50 PCN 50 F/D/X/U MIRL

RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 49'. 1.8% down.

RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 47'. 1.8% up.

SERVICE: FUEL 100LL, JET A LGT ACTVT REIL Rwy 05 and Rwy 23;

PAPI Rwy 05 and Rwy 23; MIRL Rwy 05-23—CTAF.

AIRPORT REMARKS: Attended 1500-0000Z†. Full svc fuel. Aft hrs call 307-326-8344. Antelope may be on rwy. Wind shear over highway approach end of Rwy 23. Lndg fee: turbine & jet acft only. Fees vary based on cat of acft.

AIRPORT MANAGER: 307-326-8344

WEATHER DATA SOURCES: AWOS-3PT 118.175 (307) 326-5387.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **DENVER CENTER APP/DEP CON** 132.1

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE CPR.

CHEROKEE (VH) (H) VOR/DME 115.0 CKW Chan 97 N41°45.34' W107°34.92' 104° 38.8 NM to fld. 7050/15E.


VOR unusable:

000°-015° byd 40 NM

082°-085° byd 40 NM

114°-116° byd 40 NM

125°-135° byd 40 NM



CHEYENNE
H-3E, L-9E, 11E
IAP

SHERIDAN CO (SHR)(KSHR) 2 SW UTC-7(-6DT) N44°46.15' W106°58.82'

4021 B TPA—See Remarks Class I, ARFF Index A NOTAM FILE SHR MON Airport

RWY 15-33: H8301X100 (ASPH-PFC) S-60, D-75, 2S-95

PCR 260 F/C/X/U HIRL

RWY 15: REIL. PAPI(P4L)—GA 3.0° TCH 50'. 0.5% down.

RWY 33: MALSR. PAPI(P4L)—GA 3.0° TCH 54'. 0.4% up.

RWY 06-24: H5039X75 (ASPH-GRVD) S-36, D-50 PCR 250 F/B/X/T

MIRL 1.6% up SW

RWY 06: REIL. PAPI(P4L)—GA 4.0° TCH 57'.

RWY 24: REIL. PAPI(P4L)—GA 3.0° TCH 39'. Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 06: TORA-5039 TODA-5039 ASDA-5039 LDA-5039

RWY 15: TORA-8301 TODA-8301 ASDA-8301 LDA-8301

RWY 24: TORA-5039 TODA-5039 ASDA-5039 LDA-5039

RWY 33: TORA-8301 TODA-8301 ASDA-8301 LDA-8301

SERVICE: S4 FUEL 100, JET A, A1+ OX 1, 2, 3 LGT ACTVT MALSR

Rwy 33; REIL Rwy 06, 24, and 15; PAPI Rwy 06, 24, 15, and 33;

HIRL Rwy 15-33; MIRL Rwy 06-24—CTAF.

AIRPORT REMARKS: Attended dalgt hrs. Pilots conducting EFVS ops; be aware LED ALS in use Rwy 33. Conds not monitored at ngt aft the last acr arr til 0500L. See NOTAMS for the most up-to-date conds and updts. Cold temperature airport. Altitude correction required at or below -18C. PPR unscheduled acft ops with more than 30 passenger seats ctc ARFF station 307-673-1875. Fixed wing acft rstd to rwys and twys only. TPA—4821(800) for single engine, and 5521(1500) for turboprop and jet.

AIRPORT MANAGER: 307-674-4222

WEATHER DATA SOURCES: ASOS 135.175 (307) 288-0855. SAWRS 1100-0600Z†.

COMMUNICATIONS: CTAF/UNICOM 123.0

RCO 122.5 (CASPER RADIO)

® **SALT LAKE CENTER APP/DEP CON** 127.75

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Salt Lake ARTCC at 801-320-2568.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE SHR.

(VL) (DH) VOR/DME 113.55 SHR Chan 82(Y) N44°50.54' W107°03.67' 132° 5.6 NM to fld. 4397/10E.

VOR unusable:

146°-162° byd 40 NM


163°-270° byd 12 NM

271°-280° byd 40 NM

DME unusable:

163°-270° byd 12 NM

ILS/DME 108.7 I-SHR Chan 24 Rwy 33.



BILLINGS
H-1E, 2G, L-13D
IAP, AD