

BRIDGER MUNI (6S1) 0 W UTC-7(-6DT) N45°17.50' W108°55.54'**BILLINGS**

3720 B NOTAM FILE GTF


L-13D**RWY 16-34:** H3400X42 (ASPH) S-4 LIRL(NSTD)**RWY 16:** Thld dspld 120'. Tree.**RWY 34:** PAPI(P2L)—GA 3.0°. Thld dspld 475'. Road. Rgt tfc.**SERVICE:** **LGT** ACTIVATE LIRL Rwy 16-34, PAPI Rwy 34—CTAF.**AIRPORT REMARKS:** Unattended. Deer and waterfowl on and in/ov arpt. Rwy 16 thld relocated 120' for ngt ops only not marked. Rwy 34 dthr mkd by nrs; 2880 ft avbl for night ops. Rwy 16-34 NSTD LIRL. West side 57' from pavement edge, East side 47' from pavement edge. Each thld has 4 lgts total.**AIRPORT MANAGER:** 406-662-3505**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Billings Apch at 406-255-2798**RADIO AIDS TO NAVIGATION:** NOTAM FILE BIL.**BILLINGS (VH) (H) VORTACW** 114.5 BIL Chan 92 N45°48.51' W108°37.48' 188° 33.5 NM to fld. 3811/14E.**VOR** unusable:

146°-154° byd 40 NM

155°-165° byd 40 NM blo 11,000'

155°-165° byd 49 NM blo 18,000'


166°-173° byd 40 NM

**BROADUS** (ØØF) 3 NW UTC-7(-6DT) N45°28.23' W105°27.43'**BILLINGS**

3282 B NOTAM FILE GTF

L-13E**RWY 10-28:** H4400X75 (ASPH) S-12.5 MIRL 0.4% up W**RWY 10:** PAPI(P2L)—GA 3.0° TCH 25'. Rgt tfc.**RWY 28:** PAPI(P2L)—GA 3.0° TCH 25'.**SERVICE:** **FUEL** 100LL, JET A **LGT** MIRL Rwy 10-28, PAPI Rwy 10 and

Rwy 28 opr dusk-1700, after 1700 ACTIVATE—CTAF.

AIRPORT REMARKS: Unattended.**AIRPORT MANAGER:** 406-853-6448**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MLS.**MILES CITY (VH) (DH) VORW/DME** 112.1 MLS Chan 58 N46°22.93' W105°57.21' 150° 58.5 NM to fld. 2666/9E.**BROADWATER CO** (See TOWNSEND on page 148)