

WHITEVILLE

COLUMBUS CO RGNL (CPC)(KCPC) 3 S UTC-5(-4DT) N34°16.37' W78°42.90'

CHARLOTTE

H-9C, 12H, L-35A

IAP

99 B NOTAM FILE CPC

RWY 06-24: H5500X75 (ASPH) S-45, D-60 MRL 0.5% up SW

RWY 06: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Trees.

RWY 24: REIL. PAPI(P2L)—GA 3.25° TCH 42'. Trees.

SERVICE: FUEL 100LL, JET A1+ LGT Actvt REIL Rwy 06 & 24; MRL Rwy 06-24—CTAF. PAPI Rwy 06 & 24 on consly.

AIRPORT REMARKS: Attended Mon-Sat 1300-2300Z, Sun 1400-2300Z.

Deer and turkeys on and invof arpt. Fuel 24 hr credit card svc avbl. For emergency service after hrs call 910-654-3389 or 910-625-5489.

Arpt unatndd Easter Sunday, 4th July, Thanksgiving Day, Christmas Eve and Christmas Day. No off-pavement ldg allowed.

AIRPORT MANAGER: 910-642-6187

WEATHER DATA SOURCES: AWOS-3 118.375 (910) 642-7508.

COMMUNICATIONS: CTAF/UNICOM 122.8

® MYRTLE BEACH APP/DEP CON 119.2 (1100-0400Z)

® JACKSONVILLE CENTER APP/DEP CON 134.375 (0400-1100Z)

CLEARANCE DELIVERY PHONE: For CD ctc Myrtle Beach Apch at 843-477-2727 or 843-477-2704, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.

RADIO AIDS TO NAVIGATION: NOTAM FILE FLO.

FLORENCE (H) (H) VORTACW 115.2 FLO Chan 99 N34°13.98'

W79°39.43' 090° 46.9 NM to fld. 104/3W.

TACAN AZIMUTH unusable:

200°-025° byd 30 NM blo 4,000'

VOR unusable:

089°-125° byd 30 NM blo 3,000'

126°-194° byd 10 NM

195°-223° byd 10 NM blo 4,000'


219°-229° byd 25 NM blo 13,000'

345°-360° byd 10 NM

DME unusable:

200°-025° byd 30 NM blo 4,000'

CAMP NDB (MHW) 227 CPC N34°16.39' W78°42.72' at fld. 79/7W. NOTAM FILE CPC. NDB unmonitored Mon-Sat 2300-1300Z and Sun 2300-1400Z.



WHITFIELD FARMS (See HURDLE MILLS on page 322)

WILKES CO (See NORTH WILKESBORO on page 340)