
RANCHO MURIETA (RIU)(KRIU) 1 W UTC-8(-7DT) N38°29.21' W121°06.17'
144 TPA—944(800) NOTAM FILE RIU
RWY 04-22: H3798X75 (ASPH)

SAN FRANCISCO
L-2F, 3A

RWY 04: VASI(V2L)—GA 3.0° TCH 12'. Road. Rgt ttc.

RWY 22: VASI(V2L)—GA 3.0° TCH 12'. Tree.

SERVICE: FUEL 100LL, JET A LGT Rwy 04 VASI OTS indef. Arpt lgts opr 1600-0100Z†.

NOISE: Rwy 22 noise abatement procedures in effect, ctc arpt manager 916-354-2940.

AIRPORT REMARKS: Attended 1600-0100Z†. Deer on and invof rwy. +30' obstruction lit power poles parallel to Rwy 04-22.

All ultralights must comply with FAR 103 and have an operating acft radio. All transient acft rqrd to park in designated transient area. Ldg fees apply. Pstn single \$25, pstn twin \$40, turbo prop \$75, jet \$100.

AIRPORT MANAGER: 916-354-2940

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-6874.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAC.

SACRAMENTO (VH) (H) VORTACW 115.2 SAC Chan 99 N38°26.62' W121°33.10' 066° 21.3 NM to fld. 3/17E.

VOR unusable:

031°-041° byd 40 NM blo 5,000'

031°-041° byd 45 NM blo 18,000'

157°-169° byd 40 NM blo 4,500'

157°-169° byd 56 NM blo 18,000'

246°-251° byd 40 NM

252°-262° byd 40 NM blo 7,000'

252°-262° byd 65 NM

263°-269° byd 40 NM

353°-013° byd 40 NM blo 5,000'

353°-013° byd 49 NM blo 5,500'

353°-013° byd 58 NM

RAND MOUNTAIN N35°20.32' W117°41.02'
RCO 122.4 (RIVERSIDE RADIO)

LOS ANGELES
L-7C

RAVENDALE (O39) 0 N UTC-8(-7DT) N40°48.22' W120°21.97'
5306 TPA—6106(800) NOTAM FILE RNO
RWY 17-35: H2607X30 (ASPH)

KLAMATH FALLS

RWY 35: Thld dsplcd 394'. Pole.

AIRPORT REMARKS: Unattended. Unpaved areas extremely soft when wet.

AIRPORT MANAGER: 530-251-8289

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.
